

SECURITY CLASSIFICATION OF THIS PAGE /When Date A LEAD INSTRUCTIONS REPORT DOCUMENTATION PAGE TORE COMPLETING FORM ECIPIENT'S CATALOG HUMBER L REPORT HUMBER TYPE OF REPORT & PERIOD COVERED 4. TITLE (and Subsiste) Phase I Inspection Report Phase I Inspection Report .. Main Mill Dam --National Dam Safety Program Lower Champlain Basin, Clinton County, NY 6. PERFORMING ORG. REPORT HUMBER Inventory No. NY00262 B. CONTRACT OR GRANT NUMBER(a) 7. AUTHOR(+) S GEORGE KOCH DACW51-79-C-0001 MA11016 PROGRAM ELEMENT, PROJECT. 9. PERFORMING ORGANIZATION HAME AND ADDRESS New York State Department of Environmental: 50 Wolf Road Conservation Albany, New York 12233 IL CONTROLLING OFFICE NAME AND ADDRESS 12. REPORT DAT Department of the Army 21 September 1981 26 Federal Plaza New York District, Coff 10287 New York, New York 14. MONITORING AGENCY NAME & ADDRESSIT different In-Controlling Office) 15. SECURITY CLASS, (of the report) . Department of the Army 26 Federal Plaza New York District, CofE ENCLASSIFIED New York, NY 10287 15a DECLASSIFICATION/DOWNGRADING 16. DISTRIBUTION STATEMENT (of this Report) approved for public release; Distribution unlimited. JAN 27 1982 17. DISTRIBUTION STATEMENT (of the obstroct entered in Mock 20, If ditte 18. SUPPLEMENTARY NOTES. is. KEY WORDS (Continue on reverse side if necessary and lamily by block number) Dam Safety National Dam Safety Program Main Mill Dam. Visual Inspection Clinton County, NY Hydrology, Structural Stability · Lower Champlain Basin !-ABSTRACT (Continue an reverse side if nuclearly and identity by block number) This report provides information and analysis on the physical condition of the dam as of the report date. Information and analysis are based on visual inspection of the dam by the performing organization. Visual inspection of this dam did not reveal conditions which constitute an immediate hazard to human life or property. However, the dam has some deficiencies which require further engineering investigations and remedial work. I next page DD 1 July 73 3473 Cornonior 1 Hon es is ossorase

SECURITY CLASSIFICATION OF THIS PAGE (Man Born Born


CURITY CLASSIFICATION OF THIS PADERTION Date Manual

Structural stability analyses performed for this report indicate that the spillway section is unstable for all conditions studied. The analysis was based on the limited information available and so may not reflect existing conditions. However, the analysis does indicate that there is a serious question concerning the stability of this dam and further investigations are required.

It is recommended that within 3 months of the date of notification of the owner, investigations into the structural stability deficiencies should be commenced. These studies should include developing accurate cross sections of the dam, progressing subsurface explorations, and coring the dam. This information should then be incorporated into a detailed stability evaluation and the need for modifications to the structure should be determined. Required changes of the structure should be completed within 18 months.

The spillway, while only having sufficient capacity to discharge 20% of the Probable Maximum Flood (PMF) is considered to be inadequate. For such a large storm event, a high tailwater condition would occur, resulting in the flooding of downstream hazard area. Hence, dam failure during a large storm event would not significantly increase the hazard to loss of life downstream from that which would exist just before overtopping failure.

CHAPTY CLASSIFICATION OF THIS PAGETON Buts Bullion



#### PREFACE

This report is prepared under guidance contained in the Recommended Guidelines for Safety Inspection of Dams, for Phase I Investigations. Copies of these guidelines may be obtained from the Office of Chief of Engineers, Washington, D.C. 20314. The purpose of a Phase I Investigation is to identify empeditiously those dams which may pose hazards to human life or property. The assessment of the general condition of the dam is based upon available data and visual inspections. Detailed investigation, and enalyzes involving topographic mapping, subsurface investigations, testing, and detailed computational evaluations are beyond the scope of a Phase I Investigation; however, the investigation is intended to identify any need for such studies.

In reviewing this report, it should be realized that the reported condition of the dam is based on observations of field conditions at the time of inspection along with data available to the inspection team. In cases where the reservoir was lowered or drained prior to inspection, such action, while improving the stability and safety of the dam, removes the normal load on the structure and may obscure certain conditions which might otherwise be detectable if inspected under the normal operating environment of the structure.

It is important to note that the condition of a dam depends on mamerous and constantly changing internal and external conditions, and is evolutionary in nature. It would be incorrect to assume that the present condition of the dam will continue to represent the condition of the dam at some point in the future. Only through frequent inspections can unsafe conditions be detected and only through continued care and maintenance can these conditions be prevented or corrected.

Phase I inspections are not intended to provide detailed hydrologic and hydraulic analyses. In accordance with the established Guidelines, the Spillway Test flood is based on the estimated "Probable Maximum Flood" for the region (greatest reasonably possible storm runoff), or fractions thereof. Because of the magnitude and rarity of such a storm event, a finding that a spillway will not pass the test flood should not be interpreted as necessarily posing a highly inadequate condition. The test flood provides a measure of relative spillway capacity and serves as an aide in determining the need for more detailed hydrologic and hydrolic studies, considering the size of the dam, its general condition and the downstream damage potential.

Acces	sion For			
NTIS	GRAAI		7	
DTIC	TAB	T		
Unann	ounced		1	
Justi	fication_			
By Distr	ibution/			
·	lability (	Codes		
	Avail and	or _		
Dist	Special		i	
0		·	<del>/</del>	
			DEIG	1
		1	der	
			MATERIAL	/

PHASE I INSPECTION REPORT NATIONAL DAM SAFETY PROGRAM MAIN MILL DAM I.D. NO. NY-262 DEC #236A-234 LAKE CHAMPLAIN BASIN CLINTON COUNTY, NEW YORK

# TABLE OF CONTENTS

		PAGE NO.
• ,	ASSESSMENT	, •
-	OVERVIEW PHOTOGRAPH	•
1	PROJECT INFORMATION	1
1.1	GENERAL	1
1.2	DESCRIPTION OF PROJECT	1
1.3	PERTINENT DATA	2
2	ENGINEERING DATA	4
2.1	GEOTECHNICAL DATA	4
2.2	DESIGN RECORDS	4
2.3	CONSTRUCTION RECORDS	4
2.4	OPERATIONS RECORDS	4
2.5	EVALUATION OF DATA	4
3	VISUAL INSPECTION	5
3.1	FINDINGS	\$
3.2	EVALUATION OF OBSERVATIONS	6
4	OPERATION AND MAINTENANCE PROCEDURES	7
4.1	PROCEDURES	7
4.2	MAINTENANCE OF DAM	7
4.3	WARNING SYSTEM IN EFFECT	7
4.4	EVALUATION	7

5		HYDROLOGIC/HYDRAULIC	8
	5.1	DRAINAGE AREA CHARACTERISTICS	8
	5.2	ANALYSIS CRITERIA	8
	5.3	SPILLMAY CAPACITY	9
	5.4	RESERVOIR CAPACITY	9
	5.5	FLOODS OF RECORD	9
	5.6	OVERTOPPING POTENTIAL	9
	5.7	EVALUATION	10
6		STRUCTURAL STABILITY	11
	6.1	EVALUATION OF STRUCTURAL STABILITY	11
7		ASSESSMENT/RECOMMENDATIONS	13
	7.1	ASSESSMENT	13
	7.2	RECOMMEND MEASURES	14

# APPENDICES

- PHOTOS
  VISUAL INSPECTION CHECKLIST
  HYDROLOGIC/NYBRAULIC ENGINEERING DATA AND COMPUTATIONS
  STABILITY COMPUTATIONS
  REFERENCES
  DRAWINGS ABCDEF

# PHASE I INSPECTION REPORT NATIONAL DAM SAFETY PROGRAM

Name of Dam:

Main Mill Dam

(I.D. No. NY-262)

State Located:

New York

County:

Clinton

Watershed:

Lake Champlain Basin

Stream:

Saranac River

Date of Inspection:

June 16, 1981

#### <u>ASSESSMENT</u>

Visual inspection of this dam did not reveal conditions which constitute an immediate hazard to human life or property. However, the dam has some deficiencies which require further engineering investigations and remedial work.

Structural stability analyses performed for this report indicate that the spillway section is unstable for all conditions studied. The analysis was based on the limited information available and so may not reflect existing conditions. However, the analysis does indicate that there is a serious question concerning the stability of this dam and further investigations are required.

It is recommended that within 3 months of the date of notification of the owner, investigations into the structural stability deficiencies should be commenced. These studies should include developing accurate cross sections of the dam, progressing subsurface explorations, and coring the dam. This information should then be incorporated into a detailed stability evaluation and the need for modifications to the structure should be determined. Required changes of the structure should be completed within 18 months.

The spillway, while only having sufficient capacity to discharge 20% of the Probable Maximum Flood (PMF) is considered to be inadequate. For such a large storm event, a high tailwater condition would occur, resulting in the flooding of downstream hazard area. Hence, dam failure during a large storm event would not significantly increase the hazard to loss of life downstream from that which would exist just before overtopping failure.

Other deficiencies noted should be corrected within 12 months of the date of notification of the owner. Among the required actions are the following:

1. Cut trees and brush growing on the non-overflow embankment section at the left end of the dam.

- 2. Investigate the area where the sanitary sewer line goes through the embankment to assure that the backfill material is sufficiently impervious.
- 3. Develop an emergency action plan for the notification and evacuation of downstream residents.

James Koch

George Koch
Chief, Dam Safety Section
New York State Department
of Environmental Conservation
NY License No. 45937


Col. W.M. Smith Jr. New York District Engineer

Approved By:

Carried Street

Date:

20501081



The second of th

OVERVIEW MAIN MILL DAM I.D. NO. NY262

c. Size Classification
This dam is 26 feet high and has a storage capacity of 1413 acre-feet.
Therefore, the dam is in the intermediate size category as defined by the "Recommended Guidelines for Safety Inspection of Dams."

d. Hazard Classification
The dam is classified as "high" hazard due to the presence of a trailer park and substantial development, including the City of Plattsburgh, downstream of the dam.

e. Ownership
This dam is owned by the Imperial Paper Company. The company's address is Underwood Avenue, Plattsburgh, New York 12901. Mr. George La Tulippe is the Chief Engineer for the plant. His assistant is Mr. Roy McGee. Their phone number is (518) 563-3800.

f. Purpose of Dam
This dam impounds a reservoir used for the generation of electrical power. The electricity generated is used by the owner.

g. Design and Construction History
There was no information available concerning the original design or construction of this dam. An old inspection report indicated that the dam was built in 1909 by John J. Cunningham.

h. Normal Operating Procedures
There are no prescribed operating procedures for this structure. The flashboards on the spillway section remain in place year round.

#### 1.3 PERTINENT DATA

a. Urainage Area	pos squ	are miles
b. Discharge at Dam	Water Surface Elev.	(cfs)
Spillway:	193.8	15,820
	190.3	6,420
Flood Gate (fully open):	188.5 193.8 186.0	2,846 2,146 1,415
Powerhouse:		-

C. Elevation Top-of-Dam (@ Left embankment) Top-of-Closed Flood Gate	(USGS Datum) 193.8 190.3
Top-of-Flashboards	188.5
Spillway Crest	186.0
Flood Gate-sill	174.0
d. Reservoir-Surface Area Spillway Crest	(acres) 83.6
e. Storage Capacity	(acre-feet)
Top-ot-Dam	1413
Top-of-Flashboards	970
Spillway Crest	761
Flood Gate-Sill	310
<ul> <li>f. Dam</li> <li>Type - Concrete and masonry spillway gravity section; embankment section with core wall at left end of dam</li> <li>Dam Length (ft)</li> </ul>	715
g. Spillway	
Type - Concrete and masonry overflow weir with 2.5 feet of flashboards across entire crest	
Length (ft)	225
h. Sluice Gates  Type- Two timber and steel channel gates controlled by electric mechanism located above gates	
Sime of Cates (annuovimate)	5' x 12'
Size of Gates (approximate)	9 X 14

#### SECTION 2: ENGINEERING DATA

#### 2.1 GEOTECHNICAL DATA

a. Geology
The Main Mill Dam is located in the Champlain lowlands physiographic province of New York State. The Champlain Lake Plain is a low, relatively flat area underlain with marine clays and limestone. Drift deposits and peat bogs are common in the northeast portion of the plain. Bedrock in the area is from the Ordovician era (435 to 500 million years ago). A review of the Brittle Structures Map of New York indicates that there is a topographic linear feature in the vicinity of the dam.

Surficial soils in the area are the result of glaciations during the Cenozoic Era, the last of which was the Wisconsin glaciation.

b. Subsurface Investigations
No records of any subsurface investigations performed in the vicinity
of this structure could be located.

#### 2.2 DESIGN RECORDS

No design records for this structure could be located.

#### 2.3 CONSTRUCTION RECORDS

The only information available concerning the construction of this dam was included on a Conservation Commission inspection report, a copy of which has been included in Appendix F. This report states that the dam was constructed by John J. Cunningham. The report was prepared by Mr. Cunningham and included sketches of the dam.

#### 2.4 OPERATIONS RECORDS

There were no operations records available for this structure.

#### 2.5 EVALUATION OF DATA

Data used for the preparation of this report was obtained from the Department of Environmental Conservation files. The information available was very limited and analyses performed for this report had to be based on sketches from an old inspection report and on data and measurements gathered during the visual inspection.

#### SECTION 3: VISUAL INSPECTION

#### 3.1 FINDINGS

a. General
Visual inspection of the Main Mill Dam was conducted on June 16, 1981.
The weather was sunny and the temperature was in the mid-eighties. The water surface at the time of this inspection was at the level of the top of the flashboards, with some water spilling over the crest.

b. Spillway
The spillway composes the major portion of this dam. At the time of the inspection, water flowing over the flashboards made a detailed inspection of the downstream face impossible. No serious deficiencies were noted on the portions which were visible. Mr. NcKee of the Imperial Paper Company reported that a gunite-type grouting was done on the spillway section in 1975. He stated that this work significantly reduced the leakage through the masonry.

C. Non-Overflow Segment
Inspection of the nonoverflow segment, at the left end of the dam, was hampered by trees and brush growing on the embankment. The vertical alignment of this section was slightly irregular but generally satisfactory. There was no indication of any sloughing or subsidence. No seepage or wet areas were observed. There was no slope protection on the upstream slope although there was a small area of concrete paving protecting the right end of the embankment (adjacent to the sluice gates).

An excavation had been made through the embankment to install a sanitary sewer line from the plant. There was a manhole in the center of this area. The backfill material near the surface was crushed stone. It was not known whether the remainder of the backfill was compacted properly to assure the imperviousness of the embankment.

d. Sluice Gates
The sluice gates at the left end of the spillway appeared to be in satisfactory condition. There were several leaks between the timbers and the steel channels which supported them. There was also some leakage under the gates. The control mechanism, located above the gates, was in satisfactory condition. The gates were reported to be operational and are opened several times each year.

e. Powerhouse
Minor concrete deterioration was noted on several of the exterior surfaces of the powerhouse. The trashracks and two vertical slide gates on the upstream end appeared to be in satisfactory condition. There was minor wetness on the interior walls of the powerhouse but the overall condition was satisfactory.

f. <u>Downstream Channel</u>
The downstream channel below this dam is the normal river bed, having exposed bedrock and numerous boulders scattered along the bottom.

# 3.2 EVALUATION OF OBSERVATIONS

Visual observations revealed several deficiencies on this structure. The following items were noted:

- 1. Trees and brush growing on the non-overflow embankment section at the left end of the dam.
- 2. Crushed stone backfill material in the area where the sanitary sewer line had been placed through the embankment.
- 3. Minor leakage on the sluice gates between the timers and the steel channels supporting them as well as under the gates.
- 4. Minor concrete deterioration on the exterior surfaces of the power house.

### SECTION 4: OPERATION AND MAINTENANCE PROCEDURES

### 4.1 PROCEDURES

There are no prescribed operating procedures for this dam. Flash-boards remain in place on the spillway crest year round. The sluice gates are opened when the owner wants to drop the water level in the reservoir.

# 4.2 MAINTENANCE OF DAM

Normal maintenance is performed as required by the owner.

#### 4.3 MARNING SYSTEM IN EFFECT

No apparent warning system for evacuation of downstream residents is present.

#### 4.4 EVALUATION

The operation procedures for this dam are satisfactory. Some increased maintenance efforts are required to correct some of the deficiencies noted in Section 3.

#### SECTION 5: HYDROLOGIC/HYDRAULIC

#### 5.1 DRAINAGE AREA CHARACTERISTICS

The delineation of the contributing watershed to this dam is indicated on the map titled "Drainage Area Map - Main Mill Dam" (Appendix C.) The irregular but somewhat rectangular-shaped, northeast-southwest oriented watershed of some 608 square miles is comprised of relatively undeveloped lands consisting of forests, open fields, woodlands, and mountains. The slope along the Saranac River main stem is flat to moderate, with abrupt changes in elevation occurring at nine run-of-river dams located between this site and Saranac Lake. However, the hills and mountains throughout the watershed have steep slopes with those hills forming the watershed divide ranging in elevation from 2000 to 4600 feet above the reservoir.

Numerous bodies of water within the drainage basin lie primarily in the upper reaches of the watershed; these being Lake Clear, Lake Colby, the Upper Middle and Lower Saranac Lakes, Lake Kiwassa and Oseetah Lake (all within the Lake Flower subbasin) plus Rainbow Lake, Lake Kushaqua, Loon Lake, Franklin Falls Pond, Union Falls Pond and Silver Lake. The lower end of the watershed contains only Patterson Reservoir and Mead Reservoir as sizeable bodies of water.

The major tributaries to the Saranac River main stem are the North Branch of the Saranac River and Silver Lake Brook. Many smaller streams connect the numberous lakes and/or discharge directly to the main stem. There are no known flow diversions either into or out of this watershed.

# 5.2 ANALYSIS CRITERIA

No hydrologic/hydraulic information was available regarding the original design for this dam. Therefore, the analysis of the flood-water retarding capability of the dam was performed using the Corps of Engineer's HEC-1 computer program, Dam Safety version. The computer program develops inflow hydrograph using the "Snyder Unit Hydrograph" method and then reservoir and/or channel routs the hydrographs using the "Modified Puls" flood routing procedure.

The Probable Maximum Flood (PMF) reservoir routed, outflow hydrograph at the upper subbasin, controlled by the Lake Flower Dam, was input directly to the program.

The lagged hydrograph was then channel routed down the Saranac River to this site but the nine intervening run-of-river dams were not taken into account for floodwater attenuation. The resulting runoff hydrographs were then combined at this dam and flood-routed over the spillway.

The spillway design flood selected for analysis was the Probable Maximum Flood, in accordance with the Recommended Guidelines of the U.S. Army Corps of Engineers. The PMF event is that hypothetical storm event resulting from the most critical combination of rainfall, minimum soil retention, and direct runoff to a specific site that is considered reasonably possible for a particular watershed.

The Corps of Engineers' Upper Hudson and Mohawk River Basin study (ref.7) was used to obtain hydrograph parameters, rainfall loss rate values of 1.0 inches (initial) and 0.1 inches per hour (constant) and base flow parameters. Precipitation values used in the analysis were obtained from the Heather Bureau publication, HMR 33.

#### 5.3 SPILLMAY CAPACITY

The single, ungated 225 foot long, concrete and masonry spillway was analyzed for weir flow using a discharge coefficient, C, of 3.2. Although there presently exists 2.5 feet of wooden flashboards on the crest, the floodwater analysis assumed no flashboards in place. There also exists a flood gate at the left end of the spillway. The gate, with a computed discharge capacity of 2146 cfs fully open for a water surface at the spillway crest, was assumed in the closed position for the floodwater analysis. Also, no additional discharge capacity through the hydropower machinery inside the mill at the right end of the dam was included. The computed discharge capacity of the spillway is 15,820 cfs.

The flood water analysis performed for this dam indicates that the spillway does not have sufficient capacity for discharging one half the PMF. For this storm event, the peak inflow is 38,764 cfs and the peak outflow is 38,697 cfs. The PMFFpeak inflow and peak outflow are 77,528 cfs and 77,421 cfs respectively.

#### 5.4 RESERVOIR CAPACITY

The normal water surface is at or near the top-of-flashboards (elevation 188.5 -USGS). The impounded capacity at this elevation is 970 acre-feet. The storage volume between the spillway crest elevation and the top-of-flashboards is 209 acre-feet. The total surcharge storage capacity to the top-of-dam (elevation 193.8) is 652 acre-feet which is equivalent to a direct runoff depth of 0.02 inches over the entire watershed. The total storage capacity at top-of-dam is 1413 acre-feet.

#### 5.5 FLOODS OF RECORD

The maximum known flood occurring on the Saranac River was recorded at the nearby USGS gaging station, located 600 feet downstream of this dam, on April 8, 1928. The recorded discharge was 11,500 cfs. For this flow discharging entirely over the spillway, the computed water surface is 6.3 feet above the spillway crest (elevation 192.3 USGS) just 1.5 feet below the top-of-dam.

#### 5.6 OVERTOPPING POTENTIAL

Analyses using one-half the PMF storm event indicates that the spillway

does not have sufficient discharge especity. The peak outflow from one-half PMF event will evertep the dam to a computed depth of 4.42 feet. The peak outflow from the PMF event will overtop the dam to a computed depth of 18.65 feet. All storm events exceeding 20% of the PMF will result in the dam being overtopped.

#### 5.7 EVALUATION

The spillway does not have sufficient capacity for discharging the peak outflow from one half the PMF without the dam being overtopped. For such a large storm event, a high tailwater condition would most likely occur resulting in the flooding of the downstream hazard areas. Hence, the spillway capacity is not considered to be seriously inadequate since dam failure from overtopping would not significantly increase the hazard to loss of life downstream from that which would exist just before overtopping failure. Therefore, the spillway is assessed as inadequate.

# SECTION 6: STRUCTURE STREET, STY

# 6.1 EVALUATION OF STEME BOOK STORE STY

The water floring over the spillusy unde a detailed inspection of this segment of the dam impossible. Newver, no serious deficiencies were noted on the segments which were visible. Trees and brush growing on the non-overflew segment at the left end of the dam hampered the visual inspection of this area, but no serious defects were noted. The sluice getes at the left end of the spillusy appeared to be in satisfactory condition with only winor leakage under the gates. Some minor concrete deterioration was noted on the power house at the right end of the dam.

b. Data Review and Stability Evaluation
No design or construction information concerning this structure was available. A Conservation Commission Inspection Report from 1913 contained a sketch of the dam's cross section. This sketch and measurements made at the time of the inspection were used to develop the approximate cross section shown in Appendix D. The stability analysis performed for this report was based on this approximate cross section. The results of the analysis are as follows:

	Case	Overturning Safety Factor	Resultant in Middle Third	Sliding Safety Factor
a.	Normal conditions, 2.5 feet of flashboards in place, surface at top of flashboards	i 0.94	No	0.65
b.	Water surface at spillway crest (no flashboards) ice load of 5,000 lb/ft	0.81	No	0.65
c.	Flood flow; water surface at top of dam, 7.8 ft. above spillway crest	0.76	No	0.47
d.	Normal conditions as in case a. with seismic coefficient of 0.10.	0.88	No	0.51

This stability analysis indicates that the spillway section of the dam is unstable for all conditions studied. The fact that this structure has stood for eighty years indicates that the actual safety factors are substantially higher than those computed.

The analysis performed was based on the available information which may not accurately reflect the existing conditions. However, this analysis does indicate that there is a serious question concerning the stability of this dam and that further investigations are required.

The additional investigations should include developing accurate cross sections of the dam. Subsurface explorations and cores of the dam should be taken to obtain information about the structure and uplift forces acting on the foundation. A revised stability analysis should then be performed using this data. Based on the results of these analyses, the need for modifications to the structure should be determined.

c. Seismic Stability
This structure is located in Seismic Zone 3. A seismic stability analysis was performed for the dam assuming a seismic coefficient of 0.1. The results of this analysis (shown on page 11) indicate that the safety factors are below 1.0 for both overturning and sliding. Therefore, when the revised stability analysis is performed, seismic stability criteria should also be met.

#### SECTION 7: ASSESSMENT/RECOMMENDATIONS

segment of the dam.

# 7.1 ASSESSMENT

a. Safety
The Phase I inspection of the Main Mill Dam revealed several deficiencies which can affect the safety of the dam. The most serious of these deficiencies are related to the stability of the spillway

The stability analysis performed for this report indicates that the spillway section is unstable for all conditions studied. This analysis was based on the limited information available and so may not reflect existing conditions. However, the analysis does indicate that there is a serious question concerning the stability of this dam and further investigations are required.

The spillway, while not having sufficient discharge capacity for passing one-half of the Probable Maximum Flood, is considered to be inadequate. For such a large storm event, a high tailwater condition would occur, resulting in the flooding of downstream hazard areas. Hence, dam failure during a large storm event would not significantly increase the hazard to loss of life downstream from that which would exist just before overtopping failure.

b. Adequacy of Information
The information available, while sufficient for the preparation of the Phase I report, was deficient in several respects. No plans or design information could be located. Analyses performed for this report were based on sketches from a 1912 Conservation Commission inspection report and measurements made at the time of the inspection.

c. Need for Additional Investigation
Further analysis of the structural stability of the spillway section is required. These studies should include developing accurate cross sections of the dam, progressing subsurface explorations, and coring the dam. This information should then be incorporated into a detailed stability evaluation.

#### d. Urgency

The investigations of the structural stability should be commenced within 3 months of the date of notification of the owner. Remedial measures deemed necessary as a result of this investigation should be completed within 18 months. Other deficiencies noted should be corrected within 12 months of the date of notification.


# 7.2 <u>RECOMMENDED MEASURES</u>

- 1. Modify the structure as necessary, based on the stability analysis.
- 2. Cut trees and brush growing on the non-overflow embankment section at the left end of dam.
- 3. Investigate area where the sanitary sewer line goes through the embankment to assure that the backfill material is sufficiently impervious.
- 4. Develop an emergency action plan for the notification and evacuation of downstream residents.






1913 PHOTO OF DOWNSTREAM FACE OF STRUCTURE




CURRENT PHOTO OF DOWNSTREAM FACE OF STRUCTURE



DOWNSTREAM FACE OF SPILLWAY SECTION



DOWNSTREAM FACE OF SPILLWAY SECTION



UPSTREAM VIEW OF POWERHOUSE



DOWNSTREAM VIEW OF POWER HOUSE



SLUICE GATE STRUCTURE AT END OF SPILLEAY SECTION



SLUICE GATES, NOTE MINOR LEAKAGE AT EDGES OF GATES



NON-OVERFLOW EMBANKMENT SECTION AT LEFT END OF SPILLWAY



NON-OVERFLOW EMBANKMENT SECTION LOOKING BACK AT SPILLWAY CRUSHED STONE IN FOREGROUND IS FROM THE EXCAVATION FOR THE SEWER LINE

APPENDIX B
VISUAL INSPECTION CHECKLIST

# VISUAL INSPECTION CHECKLIST

General
Name of Dam MAN MILL DAM
Fed. I.D. # 262 DEC Dam No. 236A-234
River Basin LAKE CHAMPLAIN
Location: Town PLATTSBURGH County CLINTON
Stream Name SARANAC RIVER
Tributary of
Latitude (N) 44° 41' Longitude (W) 73° 28.4'
Type of Dam CONCRETE & MASONRY
Hazard Category
Date(s) of Inspection 6/16/81
Weather Conditions SURNY 85°
Reservoir Level at Time of Inspection AT FLASHBOARD CREST
Inspection Personnel R.L. WARRENDER W.C. LYNICK
Persons Contacted (Including Address & Phone No.)  Roy McKee - Imperial Paper Company  UNDER Wood Are
Persons Contacted (Including Address & Phone No.)  Roy McKee - IMPERIAL PAPER COMPANY
Persons Contacted (Including Address & Phone No.)  Roy McKee - Imperial Paper Company  UNDER Wood Are
Persons Contacted (Including Address & Phone No.)  Roy McKee - Imperial Paper Company  UNDERWOOD AVE  PLATTS BURG NEW YORK
Persons Contacted (Including Address & Phone No.)  Roy McKee - Imperial Paper Company  UNDERWOOD AVE  PLATTSBORG New York  518-563-3800

8.	Cher	esteristics
	(1)	Embendment Material - UNKNOWN -
	(2)	Cutoff Type CORE WALL EXTENDS INTO FOUNDATION
	(3)	Impervious Core CORE WALL - UNKNOWN COMPOSITION
	(4)	Internal Drainage System NoNE
	(5)	Miscellaneous
b.	Cres	t - 10 Ft WIDE
	(1)	Vertical Alignment SLIGHTLY TRREGULAR
	(2)	Horizontal Alignment SATISFACTORY
	(3)	Surface Cracks NONE
	(4)	Miscellaneous MANHOLE CONTAINING PIPE FROM SANITARY SEWER
	PLAN'	T IS ON EMBANHMENT BACKFILL ON TOP IS CRUSHED STONE
e.	Upst	ream Slope
	(1)	Slope (Estimate) (V:H)   low Z
	(2)	Undesirable Growth or Debris, Animal Burrows Some BRUSH & TREES
	(3)	Sloughing, Subsidence or Depressions None

(4)	Slope Protection No REGULAR PROTECTION ACROSS
	SLOPE - THERE IS SOME CONCRETE ON SLOPE + CREST AT &
	OF EMBANTMENT ADJRCENT TO SMELWAY SECTION
(5)	11.000.000
Down	stream Slope
(1)	Slope (Estimate - V:H)   ON Z
(2)	Undesirable Growth or Debris, Animal Burrows SUASTANTIAL
	AMOUNT OF GROWTH-BRUSH & TREES
(3)	Sloughing, Subsidence or Depressions None NoteD
(4)	Surface Cracks or Movement at Toe NONE
(5)	Seepage NONE
(6)	External Drainage System (Ditches, Trenches; Blanket)  None
(7)	Condition Around Outlet Structure STATISFACTORY

.

.

	/80) (1)	Erosion at Contact None
	(-)	
	(2)	Seepage Along Contact NONE
	_	System
۵.	Desc	ription of System NONE
b.	Cond	ition of System
c.	Disc	harge from Drainage System
Ins	trume	ntation (Momumentation/Surveys, Observation Wells, Weirs,
Pi		ters, Etc.)  TAFF GAGE AT POWER HOUSE
		NAP CHEE IN SOUR HOUSE
	عحر	S GAGE 600 FEET DOWNSTREAM OF DAM
يحسيب		

•

	Slopes OKAY
a.	STODES
b.	Sedimentation No APPARENT PROBLEMS
c.	Umusual Conditions Which Affect Dam POND AREA IS FENCED OFF TO BPREVENT ACCESS
<u>La</u>	a Downstream of Dam
<b>a.</b>	PLATTS BURG
b.	Seepage, Unusual GrowthNone
c.	Evidence of Movement Beyond Toe of Dam None
đ.	Condition of Downstream Channel ROCK \$ BOULDER CHANNE
<u> </u>	MAIN DAM . IS OVERFLOW SPILLWAY SECTION - SCUR
<u> </u>	MAIN DAM. IS OVERFLOW SPILLWAY SECTION - SCURE HATES AT LEFT END OF SPILLWAY CAN LOWER WATER LEVEL
<u> </u>	MAIN DAM . IS OVERFLOW SPILLWAY SECTION - SCUR ATES AT LEFT END OF SPILLWAY CAN LOWER WATER LEVEL General  Condition of Bervice Spillway - FLASHBOARDS ON CREST - 2.5
	MAIN DAM · IS OVERFLOW SPILLWAY SECTION - SCUTON - FLASHBOARDS ON CREST - 2.51
	MAIN DAM . IS OVERFLOW SPILLWAY SECTION - SCUTON - FLASHBOARDS ON CREST - 2.54  ABOVE CONCRETE CREST - FLASHBOARDS STAY IN PLACE

	PLUS LEAKS ALONG CHANISM ELECTRICA	ALLY OPERATED VI
MECHANISM ABOV	E THE GATES	
_	rge Conveyance Channel	SARANAC RIVER
remoin Darin/Outlets	-SEE SLUICE GATE	s Above
		0ther
		Other
		Exit
Physical Condition	(Describe):	Unobservable
Material:		
Joints:	A1	ignment
Structural Integra	ity:	
Hydraulic Capabil:	ity:	

93-	15-	•3(	9/	'8o)
-----	-----	-----	----	------

\_ .. .

oints - Construction, etc.	
	·
oundation	
butments	
LOG LINEIT L'S	<del></del>
control Gates	
	· · · · · · · · · · · · · · · · · · ·
	·
Approach & Outlet Channels	
mergy Dissipators (Plunge Pool, etc.)	
	· · · · · · · · · · · · · · · · · · ·
Intake Structures	
	· · · · · · · · · · · · · · · · · · ·
Stability	
fiscellaneous N/A	

SLIDE GATES - A 35' DEEP FLUME - THEN THE POWER STATION CONTAINS FIVE TURBINE UNITS - TWO ARE PRESENTLY OPERAGE - THREE OTHERS USED TO BE USED TO OPERATE GRINDER THERE IS MINOR WETNESS ON THE INTERIOR WALLS OF THE POWER HOUSE - NO SERIOUS LEAKS. SOME CONCRETE DETERIORATION ON EXTERIOR WALLS BOTH UPSTREAM & DOWNSTA AS WELL.	POWER HOUSE - CONSISTS OF TRASH RACKS - 2 VER  SLIDE GATES - A 35' DEEP FLUME - THEN THE  POWER STATION CONTAINS FIVE TURBINE  UNITS - TWO ARE PRESENTLY OPERABLE - THREE  OTHERS USED TO BE USED TO OPERATE GRINDER  THERE IS MINOR WETNESS ON THE  INTERIOR WALLS OF THE POWER HOUSE - NO SERIOUS  LEAKS. SOME CONCRETE DETERIORATION ON  EXTERIOR WALLS BOTH UPSTREAM & DOWNSTR  AS WELL.  (Cheration Procedures (Lake Level Regulation):  WATER SURFACE MAINTAINED AS HIGH AS POSSIBLE	U) ADD	urtenant structures (rower nouse, Lock, Gatenbuse, Other)
SLIDE GATES - A 35' DEEP FLUME - THEN THE  POWER STATION CONTAINS FIVE TURBINE  UNITS - TWO ARE PRESENTLY OPERABLE - THREE  OTHERS USED TO BE USED TO OPERATE GRINDER  THERE IS MINOR WETNESS ON THE  INTERIOR WALLS OF THE POWER HOUSE - NO SERIOUS  LEAKS. SOME CONCRETE DETERIORATION ON  EXTERIOR WALLS BOTH UPSTREAM & DOWNSTA  AS WELL.  1) OPERATOR CLAKE LEVEL REGULATION:  WATER SURFACE MAINTAINED AS HIGH AS POSSIBLE	SLIDE GATES - A 35' DEEP FLUME - THEN THE  POUER STATION CONTAINS FIVE TURBINE  UNITS - TWO ARE PRESENTLY OPERABLE - THREE  OTHERS USED TO BE USED TO OPERATE GRINDER.  THERE IS MINOR WETNESS ON THE  INTERIOR WALLS OF THE POWER HOUSE - NO SERIOUS  LEAKS. SOME CONCRETE DETERIORATION ON  EXTERIOR WALLS BOTH UPSTREAM & DOWNSTR  AS WELL.  1) OPERATOR PROCEDURES (Lake Level Regulation):  WATER SURFACE MAINTAINED AS HIGH AS POSSIBLE	a.	
POUER STATION CONTAINS FIVE TURBINE  UNITS - TWO ARE PRESENTLY OPERABLE - THREE  OTHERS USED TO BE USED TO OPERATE GRINDER  THERE IS MINOR WETNESS ON THE  INTERIOR WALLS OF THE POWER HOUSE - NO SERIOUS  LEAKS. SOME CONCRETE DETERIORATION ON  EXTERIOR WALLS BOTH UPSTREAM & DOWNSTA  AS WELL.  1) COPERATION PROCEDURES (Lake Level Regulation):  WATER SURFACE MAINTAINED AS WIGH AS POSSIBLE	POUER STATION CONTAINS FIVE TURBINE  UNITS - TWO ARE PRESENTLY OPERABLE - THREE  OTHERS USED TO BE USED TO OPERATE GRINDERS  THERE IS MINOR WETNESS ON THE  INTERIOR WALLS OF THE POWER HOUSE - NO SERIOUS  LEAKS. SOME CONCRETE DETERIORATION ON  EXTERIOR WALLS BOTH UPSTREAM & DOWNSTR  AS WELL.  1) COPERATION PROCEDURES (Lake Level Regulation):  WATER SURFACE MAINTAINED AS WAH AS POSSIBLE		POWER HOUSE - CONSISTS OF TRASH RACKS - 2 VER
UNITS - TWO ARE PRESENTLY OPERABLE - THREE  OTHERS USED TO BE USED TO OPERATE GRINDER  THERE IS MINOR WETNESS ON THE  INTERIOR WALLS OF THE POWER HOUSE - NO SERIOUS  LEAKS. SOME CONCRETE DETERIORATION ON  EXTERIOR WALLS BOTH UPSTREAM & DOWNSTA  AS WELL.  (1) Operation Procedures (Lake Level Regulation):  WATER SURFACE MAINTAINED AS HIGH AS POSSIBLE	UNITS - TWO ARE PRESENTLY OPERABLE - THREE  OTHERS USED TO BE USED TO OPERATE GRINDER:  THERE IS MINOR WETNESS ON THE  INTERIOR WALLS OF THE POWER HOUSE - NO SERIOUS  LEAKS. SOME CONCRETE DETERIORATION ON  EXTERIOR WALLS BOTH UPSTREAM & DOWNSTR  AS WELL.  (1) OPERATOR PROCEDURES (Lake Level Regulation):  WATER SURFACE MAINTAINED AS HIGH AS POSSIBLE		SLIDE GATES - A 35' DEEP FLUME - THEN THE
UNITS - TWO ARE PRESENTLY OPERABLE - THREE  OTHERS USED TO BE USED TO OPERATE GRINDER  THERE IS MINOR WETNESS ON THE  INTERIOR WALLS OF THE POWER HOUSE - NO SERIOUS  LEAKS. SOME CONCRETE DETERIORATION ON  EXTERIOR WALLS BOTH UPSTREAM & DOWNSTA  AS WELL.  (1) Operation Procedures (Lake Level Regulation):  WATER SURFACE MAINTAINED AS HIGH AS POSSIBLE	UNITS - TWO ARE PRESENTLY OPERABLE - THREE  OTHERS USED TO BE USED TO OPERATE GRINDER:  THERE IS MINOR WETNESS ON THE  INTERIOR WALLS OF THE POWER HOUSE - NO SERIOUS  LEAKS. SOME CONCRETE DETERIORATION ON  EXTERIOR WALLS BOTH UPSTREAM & DOWNSTR  AS WELL.  (1) OPERATOR PROCEDURES (Lake Level Regulation):  WATER SURFACE MAINTAINED AS HIGH AS POSSIBLE		POWER STATION CONTAINS FIVE TURBINE
OTHERS USED TO BE USED TO OPERATE GRINDER  THERE IS MINOR WETNESS ON THE  INTERIOR WALLS OF THE POWER HOUSE - NO SERIOUS  LEAKS. SOME CONCRETE DETERIORATION ON  EXTERIOR WALLS BOTH UPSTREAM & DOWNSTA  AS WELL.  (Lake Level Regulation):  WATER SURFACE MAINTAINED AS WAY AS POSSIBLE	OTHERS USED TO BE USED TO OPERATE GRINDERS  THERE IS MINOR WETNESS ON THE  INTERIOR WALLS OF THE POWER HOUSE - NO SERIOUS  LEAKS. SOME CONCRETE DETERIORATION ON  EXTERIOR WALLS BOTH UPSTREAM & DOWNSTR  AS WELL.  (Lake Level Regulation):  WATER SURFACE MAINTAINED AS WAY AS POSSIBLE		
THERE IS MINOR WETNESS ON THE  INTERIOR WALLS OF THE POWER HOUSE - NO SERIOUS  LEAKS. SOME CONCRETE DETERIORATION ON  EXTERIOR WALLS BOTH UPSTREAM & DOWNSTA  AS WELL.  (peration Procedures (Lake Level Regulation):  WATER SURFACE MAINTAINED AS HIGH AS POSSIBLE	THERE IS MINOR WETNESS ON THE  INTERIOR WALLS OF THE POWER HOUSE - NO SERIOUS  LEAKS. SOME CONCRETE DETERIORATION ON  EXTERIOR WALLS BOTH UPSTREAM & DOWNSTR  AS WELL.  (peration Procedures (Lake Level Regulation):  WATER SURFACE MAINTAINED AS HIGH AS POSSIBLE		
INTERIOR WALLS OF THE POWER HOUSE - NO SERIOUS  LEAKS. SOME CONCRETE DETERIORATION ON  EXTERIOR WALLS BOTH UPSTREAM & DOWNSTA  AS WELL.  (peration Procedures (Lake Level Regulation):  WATER SURFACE MAINTAINED AS HIGH AS POSSIBLE	INTERIOR WALLS OF THE POWER HOUSE - NO SERIOUS  LEAKS. SOME CONCRETE DETERIORATION ON  EXTERIOR WALLS BOTH UPSTREAM & DOWNSTR  AS WELL.  (peration Procedures (Lake Level Regulation):  WATER SURFACE MAINTAINED AS HIGH AS POSSIBLE		
LEAKS. SOME CONCRETE DETERIORATION ON  EKTERIOR WALLS BOTH UPSTREAM & DOWNSTA  AS WELL.  (1) Operation Procedures (Lake Level Regulation):  WATER SURFACE MAINTAINED AS HIGH AS POSSIBLE	LEAKS. SOME CONCRETE DETERIORATION ON  EXTERIOR WALLS BOTH UPSTREAM & DOWNSTR  AS WELL.  (1) Operation Procedures (Lake Level Regulation):  WATER SURFACE MAINTAINED AS HIGH AS POSSIBLE		
EXTERIOR WALLS BOTH UPSTREAM & DOWNSTA  AS WELL.  (1) Operation Procedures (Lake Level Regulation):  WATER SURFACE MAINTAINED AS HIGH AS POSSIBLE	EXTERIOR WALLS BOTH UPSTREAM & DOWNSTR  AS WELL.  (1) Operation Procedures (Lake Level Regulation):  WATER SURFACE MAINTAINED AS HIGH AS POSSIBLE		
AS WELL.  (1) Operation Procedures (Lake Level Regulation):  WATER SURFACE MAINTAINED AS HIGH AS POSSIBLE	AS WELL.  (1) Operation Procedures (Lake Level Regulation):  WATER SURFACE MAINTAINED AS HIGH AS POSSIBLE		
11) <u>Operation Procedures</u> (Lake Level Regulation):  WATER SURFACE MAINTAINED AS HIGH AS POSSIBLE	11) <u>Operation Procedures</u> (Lake Level Regulation):  WATER SURFACE MAINTAINED AS USA AS POSSIBLE		
WATER SURFACE MAINTAINED AS HIGH AS POSSIBLE	WATER SURFACE MAINTAINED AS HIGH AS POSSIBLE		NS WELL.
WATER SURFACE MAINTAINED AS HIGH AS POSSIBLE	WATER SURFACE MAINTAINED AS HIGH AS POSSIBLE		
	WATER SURFACE MAINTAINED AS HIGH AS POSSIBLE		
WATER SURFACE MAINTAINED AS HIGH AS POSSIBLE	WATER SURFACE MAINTAINED AS HIGH AS POSSIBLE		
WATER SURFACE MAINTAINED AS HIGH AS POSSIBLE	WATER SURFACE MAINTAINED AS HIGH AS POSSIBLE		andrian Brown district and Brown and
FOR POWER GENERATION	FOR POWER GENERATION		
			FOR POWER GENERATION
		***************************************	

# APPENDIX C

HYDROLOGIC/HYDRAULIC ENGINEERING DATA AND COMPUTATIONS

# MAIN MILL DAM

#### CHECK LIST FOR DAMS HYDROLOGIC AND HYDRAULIC ENGINEERING DATA

	AREA-CAPACITY DATA:	USGS DATUM Elevation (ft.)	Surface Area (acres)	Storage Capacity (acre-ft.)
1)	Top of Dam	193.8	83,6+	1413
2)	Design High Water (Max. Design Pool)		<u>-</u>	
3)	Aunthory Spillway Crest	186.0	83.6	761
4)	Pool Level with Flashboards	188,5	83.6+	970
5)	STATUTE SPECIALLY CHOSE FLOOD GATE SUL	174.0	83.6 -	310

	DISCHARGES	<u>Volume</u> (cfs)
1)	Average Daily	UNKNOWN
2)	Spillway @ Maximum High Water	15,820
3)	Spillway @ Design High Water	•
4)	Spillway @ Auniliary Spillway Crest Elevation	2,846
5)	LOW Level Outlet - FLOOD GATE FULLY OPENED	2,146
6)	Total (of all facilities) @ Maximum High Water	15,820-
7)	Meximum Known Flood	· · · · · · · · · · · · · · · · · · ·
8)	At Time of Inspection	11,500

LEVATION: 193.8
VT
300'±
EHERGENCY
. •
·
•
nat
· ••

HIDROMETERULUGICAL GAGES:
Type: USGS GAGE # 04273500
Location: 600 ft downstream of dam
Records:
Date - APRIL 8, 1928
Max. Reading - 11,500 cfs
FLOOD WATER CONTROL SYSTEM:
Warning System: NONE
Method of Controlled Releases (mechanisms):
SLUICE GATES (ELECTRICALLY OPERATED) AT
END OF SPILLWAY

I NAGE AREA:	608 So. MT	
INAGE BASIN RUNOFF	CHARACTERISTICS:	
Land Use - Type:	ADIRONDAK MOUNTANS	
	Same T MANGATE	
	GLACIAL TILL	
Runoff Potential	(existing or planned extensive alterations (surface or subsurface conditions)	
None		
Potential Sedimen	tation problem areas (natural or men-made;	
		·
	er problem areas for levels at maximum stourcharge storage:	orage capacity
Non	IE	
•		
Dikes - Floodwall Reservoir p	s (overflow & non-overflow ) - Low reaches erimeter:	along the
Location: _	None	~
Elevation:		
Reservoir:	•	
Length @ Ma	ximum Pool	(Miles)
	boreline (A Sailline Creek)	

\*\*\*

		7		MI	LL		D.	A٨	1										SHE	1/	<b>vo.</b>				CKE				DAT				
NEC.			_		_		Ω.													•				COI	WPU		BY		DAT	TE 7/-	32	/3	
ω,	A	E	<u> S</u>	HE	D		M	RAI	ME	TE	RS	2									_			_	$\omega$	<u>_</u>			_	<u>//:</u>	23	/즉	<u>_</u>
								<u> </u>																									L
DR	Ā	NA	Ä		AR	EA																											
			,				Г		Г	Г																							
	Η	يو		_	G.P		-	#	04	<u></u>					_			17		:		AR			600	9	-	ο.	441				Г
Н	H	5	3	H	7	عو	┝	1	<u> 194</u>	41	125	Œ	┝	e	~	AM	1	17	4	-	_	AK	М	Ë	KAL	10	1	*	-	-	┪		H
	H	Н		<u> </u>	-		L	⊢	ـ	_	Ļ	_	_			<u> </u>		Н	Н		Н		Н	١	<del> </del>	-	_			Н	_	Н	⊢
Ц		52	BB	Æ	111	$\Box$	L	AK			Ьω		9	AM	7		L		Ц			A٤	EA	8	17	9	S	Q.	Z				L
						\	-		יא	_نا	70	7			<b>\</b>	l								Į	_	L	1						
							Π		Γ	7											Δ	A		*	AS	9	9	9.	M				
Н							_	<del>                                     </del>	1		1	_	_	<b>—</b>		-																	
Н	$\vdash$	H	Н	-	-	┝╌	-	-	╌	┝	H	$\vdash$	$\vdash$	-	_	┝	$\vdash$	Н	Н	_	H	-	Н	⊢	-	-	_	H		Н	-	H	-
Щ	_	Н	Щ	-	H	_	_	_	╄	_	<b>—</b>	_	_	-		<b>-</b>	Щ	Ш	Н	_	-		Н	<u> </u>	-	H	_	Н	Į	-	H	Н	۲
									L	L	<u>_</u>					L_		_				Ш	Ш		L_	_	L_	Щ				L.	L
SU	BP	æ		_	ما	JF	R		L		A	RE	A	•	4	ود	2	6	M		L		L	L			L_						L
								T	Г		Γ,														Π								Γ
H	$\vdash$		$\Box$	_			1		<b>t</b> -	<u>_</u>	<b>!</b>	<b> </b>	$\vdash$				/_		T			K			Ou	=-	Γ,	4			Т		Г
Н	H	MA	μМ	<del>  3</del>	μE	Μ.	<del>ا</del>	F	13	PK	ΑN	1	Ι-	87,	ΥE	-	۲	AM	7	ِ ن	1	لطم		₩,	NO.	لاكت	۳	14	)	•	$\vdash$		۲
Ш	<u> </u>	Ш	Щ	<u> </u>	<u> </u>	<b>-</b>	_	┞	1	┞-	Ļ	<u> </u>	<u> </u>	<b>L</b> _	<b>L</b>	<b> </b>	Ĺ	<u> </u>	Щ		<b> </b>	Щ		L	<u> </u>	_	⊢	Н	<b></b>	ļ	<b> </b>	_	-
Ш				0	אני	2		<u> </u>	L	19	CA	E	L		L	IN	يط		لبا		E		Ш	L_	<b>L</b>	_	L.		_	Щ	<u>_</u>	L.	L
				4	ጟ																				Ŀ								L
П				П	_					Г			_	П											Π								Г
H		Н	I					_	┪	1	-				_	5.					_		М	7.	ES		ī		-	40	7		Г
Н	$\vdash$		Ч	AT.	5	137	K	┝	<del> </del>	11:	24	00	P_	┝	<del> </del>	2.	2	-	Н		-	Н	-	H.		Μ.		Ė	S	40	<u> </u>	-	⊢
Щ					_	_	_	┞_	L	┞_	14	_		_		L	_	_	Щ		_		Щ	K	10	<u> </u>	25	RE	24	LP	AM	بــا	L
			M	RR	150	יאם	Vι	E			Ш				٦	4.	4							<u>\</u>	<u> </u>		L					L	L
	Г							Γ	Г	Π	П																						l
	Т		1		ΙE				T	<u> </u>	T		Г	Т	2	4.	•							Г						Г	1	Γ	Π
Н	$\vdash$	┝┈	7	1270			KA	╄╌	H	┢╌	╫	┢	┢┈	┢─	9	7.	1	-	Н		-	Н	$\vdash$	┝	<del> </del>	Н	-	H			$\vdash$	┢	t
$\vdash$	⊢	$\vdash$	Н	┞	<u> </u>	┝	├-	├	┢	┝	Н-	_	┝	┡—	├	<u> </u>	١.	-	Н		├	H	Н	┝	┥	⊢	<del>                                     </del>	Н	_	Н	⊢	├	⊢
			MC	EF	П	64	ш	E	L	Ŀ	Щ	_	_	<u>_</u>		3.	5				L.		Щ	L	_	_	<u> </u>			_		↓_	L
					Ŀ				<u>L_</u>	L	Ш													(a	4	4	7	0	d	$\rho \eta$	ΕL	$\mathbf{a}$	c
			0 C	DE	O	D	Г	П	Γ	Γ	П				ລ	7.	3							Y	W.	6	11,	Æ	2	AK	Ė	AR	5
Н	_	П	1	۳	۲	۳	<u> </u>	┢	1	1	1		Т	Ι-	_	1			_					T	17	_	_		1	<u> </u>			Г
Н	-	Н	Н	-	-	Η.	<del> </del>	⊢.	╁	-	۲.		<del>-</del>	┝	Η.	-	┢	-	Н	_	-	Н	H	17	╁		┝	Н	-	-	$\vdash$	-	H
	<b> </b>	Н	A٢	DE	R.	علا	RC	<b>PR</b>	<b>-</b>	μ.	24	$\infty$	<u>ը</u>	<u> </u>	Ц	<u>Q</u>	8	-	Н	-	-		H		9.	_	_	۵.,				0	
Ш		لـــا				_	丄	_			<u> </u>		<u></u>	L_							<u> </u>	Ш	يُـــا	Z		ÜΝ	101		ĘΔ	12	┡_	Pa	М
									L	L	L		L		و	G.	h_		<b>^</b>	19	ဩရ			/	L		L				L		L
				Г		Γ					Γ											40		11 5	5						Γ	Γ	Γ
H	<del>                                     </del>		М	Т			<del>                                     </del>	T	t	1	T	<b>—</b>	Т	<u> </u>				T	П		_		Н		ľ	_					Г		Г
Н	-	$\vdash$	<del>                                     </del>	$\vdash$	-		<del> </del>	-	┢	+	-		┢	├	┢╾		-	$\vdash$	Н	-	<del>                                     </del>	Н		<del> </del>	+-		-	$\vdash$		-	$\vdash$	<del> </del>	H
$\vdash$	<b>—</b>		LA	KE	L	ᄊ	ध्य	D.	▙	غلل	62	٥ڪا	ρ.	<b> </b>	Ι	7.	12.	H	<b> </b>	<u> </u>	-	Н	Н	<b>-</b>		-	$\vdash$	Н	Н	Ι	-	-	┝
				L_					_						_	L.,	<u> </u>	Ц.,			<u> </u>		Щ	<u> </u>	<u> </u>	_		Щ			<u> </u>	<b>_</b>	L
П			34	84	2	C.		KE		Li	62	50	b		تــا	سا	0						L	L	L								L
П					Г			Γ	Γ		Г		Г	Γ=	F			F														T	Γ
H	<del>                                     </del>	Н	-	┢	一	$\vdash$	1		✝	<del>                                     </del>	<u> </u>	1	<b>├</b>	1	٦,	6	5				1	54		<u> </u>	T								T
Н	⊢	Н	Н	├-	$\vdash$	┢	⊢	╀	╀┯	Η.	<b>}</b>	H	├-	<b>-</b>		<b>P</b> -	7	┝═	>					t	<del> </del>	$\vdash$	Η-	$\vdash$		$\vdash$	$\vdash$	┯	۲
Ш		Ш		<u> </u>	L	<b>—</b>	<b>!</b>	┡	↓_		Ļ	_	<u> </u>	┞	L	<b> </b>	₩	<b> </b>	Н	$oldsymbol{\sqcup}$	<b>5</b> -	25	Ļ۵	μī	15	-	<b>—</b>	⊢	ـــــا	<b> </b>	₩-	⊢	╀╌
L	L				L	L	L	<u>L_</u>	L	L	L		<u> </u>	L							_			<u> </u>	L			Ш			<u> </u>		L
	Γ			Γ		Γ	Π	Γ		Π		Γ							=				_		L	L	$L^{-}$		$L_{-}$		L	L	Ĺ
П	Т			T	Г		t	T	Т	Γ	1				Γ		L	-		5	4	65		11. 1	ے					Γ	Γ		Γ
┥	╁	H	$\vdash$	┢	$\vdash$	-	╁	+-	<del>                                     </del>	+-	$\vdash$	$\vdash$	H	┢	$\vdash$		1	┪	Н		1	ř	٣	٣		<b>—</b>	Т	М	┢	<del>                                     </del>	T	⇈	t
₩	}—	-	$\vdash$	┡	⊢	┝	┡	╀	╀	╀	⊬	-	<u> </u>	├-	-	╁	-	<del>  _</del>	$\vdash$	<u> </u>	<u> </u>		-	┢	<del> </del> -	┪	┢╾	$\vdash$	$\vdash$	₩	┼	╁╌	┝
Ш		_	_			<u></u>		↓_	<u>Ļ</u>	<b>L</b>	Ļ		Щ.	L.	<b>L</b>	<b>_</b> _	Je,	.=		_3	13.	75	ᄖ	Ш	12	ļ	L.	<b>—</b>	_	-	<u> </u>	┞	┞
8	1	• "					•	1			•	1		•			. C	X	1		i		•	•	1						1	•	•

. !

2
6
ĭ
Ξ
_
4
×
ũ

14. 1. 1/2.

FAGE				•	•			•	<b>-</b>		136										1 0 254	**************************************										
			•			٦.	_		· ·		1.0		•	_			-				1.0			-	1+2=2	_		1573		•		:
			c	•		9.C	•	٠.	c	108	0			<b>3</b>			3		0	108	0			င	SARANAC LAKE	0		c	,			ı
		9.5)	A 1515	•		•: •:	U		170.1	162	•		•	<b>.</b>		•	U		179.1	102	Ü				UPPER SAR	,	LAKE DAR	<u>-</u> ر	163000	50		
		PAKAPETE		•	-	4 0.5	U		(J	10 2	9	,	•			)	0	~		7 91	<u>ټ</u> ن	. •	•	ن ن	DRCCRAPHS AT		R SARANAC	<b>ں -</b> ت د	0 105000	15	5 1.5	5
	0	B (Sayotk	1940 DAG /	•			2	SUBAREA	1 22.	•	0	: : ::::::::::::::::::::::::::::::::::	29	7000 1000		, m	-	SUBAREA	1 41.		v		0	9	Z HYDRC		7 7		550C	158	~	2.65
7 . O . C	. •		•	^	-	0.2	<b>-</b>	110101	-	<b>7</b>	<b>( )</b>	6.2 6.62	7.	20116	•	! !	102	RUNDES	-	2		•	•	200	COMBINE	1 2(	3 31002			M	••••	· •
LAKE 'L(	Ŧ	<b>8</b> 5		_		5	¥	£3	£	•	-	<b>.</b>	, ,	4 S	. >	=	×	T .	=	۵.		<b>3</b>	•	<b>×</b>	-	<b>∠</b> {		. 5	•	•	157	8 2
<b></b>	(1000)	(2007)	(0007)	(000.5)	(9, 33)	()0331	(6)(3)	(6797)	(00100)	(1911)	(12)	(0013)		0016)		(018)	(6103)	(0050)	(1203)	(2700)	0023)	(624)	(5762)	(9200	(627)	(0028)	(4705)	0031)	(0032)	(6033)	(034)	(0035)

C00400 C00400 C00410 C0	,	•							
	<b>7</b>	•	-						
	0	300		ر.	<u>ن</u>	U			
	_	RUNOFF SUB	BAREA 3						
	_	~	24.0	ی	179.1	0	ပ	ن	_
56455	.3	10.	"	91	102	138	:		
1 (773)	J	ວ	ပ	9	9	0	1.0	0.1	0 .106
0045>	4.3	0.625							
x (9900	-2.0	-0.10	1.6						
	٧	300	<b>3</b>	رن	U	0	_		
OC44) K1	_	COMBINE 2	HYDRUGR	AFHS 3+	F 12				
	-	300	<u>ی</u>	ပ	ပ	0	<u>.</u>		
OC 50 K1		ROUTE OVER	R CUTLET	CONTROL	AT MIDDLE	SARANAC	4.0		
	. 7	0	U	_	_				
<u> </u>		٠	<b>3</b>	U	ں	0	-1536	0	•
2		9000	150C0	29000					
3		1540	1545	1550					
2	1534	. 35.	2.65	1.5	•				
-	1540	5.65	1.5	•	•				
2			9	0	ပ ·	0	<u>-</u>		
(0054) K1	_	BOUTE TRRE	N SARANA	C LAKE (1	OLER)			•	
¥ (6507)	• • •	<b>(3</b> )	٠	<b>5</b>	_				
	• •		<b>-</b>	,	,				
	4	707		9	ٺ	: :		:	
(6062) K1	_	BEROFF SE	BAREA 4						
Ů0∙3) n		-	23.7	Ü	179.1	U	u	u	
_	<b>ن</b> ا	-	7	- 6	102	108			
CC65) T	•		•	0	0	0	<b>1.</b> C	0.1	0 .143
	3.2	1.0							
,	7-2-0		٦.٠	:			•	•	
0068) K	IJ	2	•	0	0	0	-		
	_	Runoff St	DAREA S						
00700 H	<b>~</b>	<u>-</u> -	19.2	J	179.1	0	: •	•	•
	0	<b>16.</b>	11	-6	162	108		•	
0072) 1	9		ပ	0	<b>ں</b>	0	J.C	0.1	
	•	6.625					•	;	•
x (5233)	3.2-	-0-	1.6						
	M	70 <b>7</b>	<b>0</b>	<b></b>	ر،	ى	-		-

j

3

<b>8</b>
-
5
-
w
¥
_

(10077) K1 1 40C (10078) K1	3 K 2 C C A C	C C CONTLET TO LOWE	C SARANAC	0	-			
KI ROUTE OVER  YI I O O  SE 1533 C.65  SE 1533 C.65  KI ROUTE THRU  Y Y C CORBINE 2  KI ROUTE OVER  Y 1528 1529  Y 1528 1529  Y 1528 1529  Y 1528 1522  SE 1513 1522	13.50 C C C C C C C C C C C C C C C C C C C	01 1	<b>a</b>					
Y			ŀ	MAC				i
## 1533   1540   155000   155000   1553   1540   1553   1540   1553   1540   15500   1		_	_					
SS C 1550C SE 1533 6C SS 1533 6C K1 1537 6.65 K1 100TE THRU Y 1 100 601 K1 100 601 K1 100 601 K1 100 601 K1 100 601 K1 1528 1629 Y 1528 1529 Y 1528 1522		ဘ	<b>.</b>	9	-1533	u		
SE 1533 154C SE 1533 6C KI 16CC KI ROUTE THRU Y C 6C1 KI CORBINE 2 KI CORBINE 2 KI CORBINE 2 KI CORBINE 2 KI ROUTE OVER Y C C 0 Y 1528 1529 164C SE 1513 1522 SE 1513 2.65	25.5 2.5 2.5 2.5	51000						٠
\$\$ 1533 6CC KI 1 6CCC KI 1 6CCC KI 1 0 011 KI 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		1550						
x1 1537 2.65  x1	2.5	1.5						
K1 ROUTE THRU Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y	•	15					;	
K1 ROUTE THRU Y 1 0 601 K1 COMBINE 2 K1 COMBINE 2 K1 COMBINE 2 K1 COMBINE 2 K1 1528 1529 Y C C D Y 1528 1529 Y 1544 1546 Y C C COMBINE 2 K1 1528 1529 X4 1558 1552 SE 1513 1522 SE 1513 2.65	د	0	ပ	J	-			
Y 1 0 001  K1 COMBINE 2  K1 1528 1529  Y C C D  Y 1528 1529	OSEETAH	LAKE FLOW	<b>E</b> 3					
K1 COMBINE 2 K1 FOUNDF SUB W 1 1 16.  F 5 16.  J 6.65  N 72.0 -0.10  K1 COMBINE 2 K1 COMBINE 2 K1 1528 1529  Y4 1528 1529  Y4 1528 1529  Y5 13755 1644C  SS 1528 5.65	<b>ن</b>	ى	_					
K1 K1 C0 601  F 7 1 16.  I 6.65  N 4.6 C.625  N 7.0 -0.10  K1 C0KBINE 2  K1 C0KBINE 2  K1 1528 1529  Y4 1528 1529  Y4 1575 1644C  \$\$ 1528 5.65	~							
K1 RUNOFF SUB F 5 16. 1 6.625 A -2.0 -0.10 K1 2 600 K1 2 600 K1 600 K1 100 Y1 1528 1529 Y2 1528 1529 Y3 13755 16440 SS 1528 2.65 SS 1528 520 SS 1528	ပ	0	Ų	0	_			
H 1 16.  1	REA 6				. •	:		
F 5 16.  1		0 179	_	0	ں	ن	_	
T	-	-	20	108				
K1 COMBINE 2 K1 COMBINE 2 K1 COMBINE 2 K1 COMBINE 2 K1 F COMBINE 3	U	c	Ų	O	1.0.1	. 0.1	ن ن د	.067
K1 COMBINE 2 K1 COMBINE 2 K1 COMBINE 2 K1 FOUTE OVER Y C C O Y C C O Y 1528 1529 Y 154 1546 Y 1558 1529 X 1575 1646C SS C BEC SS	1	•	,		l •			,
K1 COMBINE 2 K1 COMBINE 2 K1 1 COMBINE 2 Y C C O Y 1 1528 1529 Y4 1528 1529 Y5 1375 1646C SS C BEC SS	1.6		•		٠			
K1 COMBINE 2 K1 1 605 K1 1 605 Y C C 0 Y 1 1 1 0 Y	U	·	S	ප	· .	:	:	•
K1 ROUTE OVER Y C C O Y 1 1 0 Y 1528 1529 Y 1544 1526 Y 1375 1644C \$\$ C 82C \$\$ C 82C \$\$ 1528 \$\$ 1528 \$\$ 1528 \$\$ 1528 \$\$ 1528 \$\$ 1528 \$\$ 1528	HYDROGRAPH	HS - INFLOR	HYDROGRA	F	FOR LAKE	FLOWER	9=7+9	
K1 C C C V V C V V C V V V C V V V V V V	0	0	Ü	0	-			
Y C C 1528 152 152 154 154 154 154 154 154 155 1644 155 1644 155 1644 155 155 155 155 155 155 155 155 155 1	LAKE FLOWER	_	,					
Y4 1528 152 Y4 1544 154 Y5 1544 154 Y5 13755 1644 SS C 82 SE 1513 152 SB 1528 SB 1528	ت	_	_					
74 1528 - 155 74 1544 154 75 13755 1644 85 1513 152 80 1533 2.6	ပ	5	J	9	-1528	-		
74 1544 154 75 0 14 75 13755 1644 85 0 82 88 1513 152 80 1533 2.6	1536	1531 153	25	1534	1536	1538	1540	1545
YS 13755 1644 \$\$ 5 5 82 \$\$ 1513 152 \$\$ 1533 2.6	1548	1550						
45 13755 1644 45 5 5 82 86 1513 152 48 1533 2.6	200	1010 162		3065	4775	6725	8880	11225
\$5 C 82 \$6 1513 152 \$6 1538 2.6 \$6 1533 2.6					;			i i
8£ 1513 152 8\$ 1528 150 1533 2.6	2800	200	_	3460	30560	4 7 0 0 C		
88 1528 1533 2 1 K 99	1525	1528 153C		1535	154	1545		
\$0 1533 2 ) K 99				٠	í	:	:	
96 X, 0	1.5	32				•		
					:			:
12)								
_								
(C112)						;		

\$ 41 B 16

PREVIEW OF SEMERIC CALCLATIONS
RUNDF EYUNGGIAPM AI
ROUTE TYDEGRAPM TO 2CO
RUNDF WYDEGRAPM AT 2CO
RUNDF WYDEGRAPM AT 2CO
RUNDF WYDEGRAPM AT 2CO
RUNDF WYDEGRAPM AT 3CO
RUNDF WYDEGRAPM AT 3CO
RUNDF WYDEGRAPM AT 3CO
RUNDF WYDEGRAPM AT 4CO

444	NEK Y	DEPT	FL 600
	;		
•		_	•

	CAN SAFETY LAST MODI	FERY VERSION 26 INTELLIGENCE	3 1	LV 1978 EB 79 APR 79								14	PEPT OF	DEPT OF ENVIRONMENTAL C FLCOD PROTECTION BUREAL	ENTAL C BUREAL	COKSERVATION L	1AT10N	:
1		• • • • • • • • • • • • • • • • • • •	A1 NY-1 A2 A3		LAKE F EEC 18 PMF	FLOWER DAW 163-1107 CHAMPLAIN 1/2 PMF PHASE	DAN 7 CHAMPL! 78F PR	LAIN T	- DALE		i.e. ivi	LAKE CHAMPLAIN BASIN FRANKLIN COUNTY	TPLATA COUNT	AMPLATE BASITE		; 		:
•	- <b> </b>			e in	m		•			•	<b>.</b>	•		-	•	i	!	•
•	•			_	N			:	• •		•							
.•	<b>.</b>	7			-				•• .					6			•	
•	•	:		~	931	•			•		~	!				! 	1	ŧ .
•	·				PURCFF	FUNCFF SUBAREA	~					!	1	!	į	:		
	<b>2</b> .	*		~	~	32.5		179.1			·			-				
!			1		16	#	16	102	. ' -	108		; ; ;			1	I	į	
	2						;	,	•		1.0	1.0		0.136	. %	ì		•
			•		.625	•					•	  -   .						
۱.	1		-2.0	•	. 0.10	1.6	!		•	,	:	; ; ;			<b>:</b>			
'	=======================================	¥	•		200		•				<b>-</b>	• !			•	; †	!	
	16		K1		FOUT 1	THRU UPPER SARANAC	ER SAR	ANAC	•									
ı	11		1	•		. *		-			•		<u> </u>		•	1	1	
,	21	•		:		,			••		į	; ;				1	· 	1
	51	¥			261	•		•	-			•						
	36	1	<b></b>	•	AUNCFF	AUNCFF. SUBAREA	~		٠,		•	1					!	•
,	21.	<b>-</b>	- ;	. ,		41.5		179.1	•'	٠		į		-			•	
	2,2				36	۲.	91	102		108	. '							
•	53								•		1.0			1.254	*	: !	•	
	24	3	9.6	•	.625	٠						:	1		ţ		• .	
		*	-2.6	7	91.10	1.6												
1		:		. ~	260		:				-					i .	† †	
	27	<b>*</b> ,			CONEINE		2 HYDROGRAPHS	Ė	IP PER	UPPER, SARANAC LAKE	C LAKE	1+2=2			1	!	1	
	. 32	**		-	200		•	•	•-	•	~		•					
•			:		1001	BOUT (VER UPPER SARANAC LAKE DAN	ER'S AR	ANAC L	IKE D'A		•	; 				!	:	
A. Carrie																		

<b>A</b>		•								<del></del>
	33		11	-			·		-1973	•
	32		\$\$	•	93092	00033	10500	163880		-
•	ž		<b>3</b> 6	1573	1517	15.80	100 to	1590		-
i :	31		:	1573	115	2.65	3.5			
•	W)	.;	3	1575	2.65	<b>1.</b>				
٥	36		¥	-	301					***
;	cs.		X		1001	SOUT THRU RIDDLE	TOOLE SI	IRANAC LAKE		
•	an .	:	-	,		•	•	-		
· .	35	••	=	•						
<b>†</b> .		;	×	<b>.</b>	360					· · ·
•	ī	1	2		2808	RUNCFF SUBAREA	REA 3			
•			=	-	-	24.0	•	119.1		er er er er er er
	P) •	1	•	:	91		. 16	1 62		i .
•	:		-						1.0 0.1	
•	**		>	4.3	6.625	٠				
; •			*	-2.0	.6.10	1.6			The same of the sa	
•	4.1	1	¥	8	366					
•	4		2		COME	CONFINE 2 HYDROGRA		PHS 3+2=3		
ļ	•	1	<b>¥</b>		300		-			
•	9.0		4		F 00.1	POUT CVE'R GUTLET	_	CONTROL AT MIDDL	I DOLE SARAKAC	
•	. 19		>				~			
,			11						9891-	
•	60		<b>\$\$</b>	•	0009	15000	29606		The state of the s	
•	40	! !	<b>*</b>	1536	1540	15 45	1550	•		ot orange,
	<b>13</b>	•	:	1536	87 F1	2.65	7.5	٠	The second secon	
•	96	:	2	1540	2.65	**	•			1
•	51.		¥	~	00+					g dage of the grades
	W	•	¥	t	100	BOUT THRU LOWER SA	OUER SA	RANAC LAKE		-
• ·	ur		-			•		-		
•	<b>.</b> ,		11	•	:					4

	***************************************		A CONTRACTOR OF THE CONTRACTOR	1.0 0.1					The second secon		1.0 0.1				DEER GARARAC U++-GRA	A Company of the Comp	IANAC		-1533 0				•					
	FF SUBAREA 4	23.7 119.1	77 91 102 108	•		1.06		CFF SUBAREA S	19.2 179.1	77 91 1.2 168		•	9. 1		EINE 3 HYDROGRAPHS - INFLOU'TO LOUER	•	JI CVER BAM AT OUTLET'TO LOWER SARANAC		•	10000 51000	1545 1558	Hotel Bott	1.5 12		THRU CSEETAH AND LAKE FLOWER		•	2 CIRABEA 6
6 ×	K1 RUNCFF	2 1 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	36	<b>₽</b>	3°2 0.625	67 x -2.0 -6.10	2	HADRON KA BONCE	26 7 1 1 1	71 P 16	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	72 B 5.4 B.625	74 x -2.0 -6.10	000 M M M M M M M M M M M M M M M M M M	76 KI COMEIN	77 K 1 489	TE KI ROUT C	A 54	. BC Y1 1	25 0 15060 1	56 1533 1540	62 55 1533 66	50 1537 2.65	999 I W	LUON KA AGE	 41 0	10g 0 X	

:			:			•	;		;	:			_ i / !		1		•				•	;	, ,	
	,		; ;			. • •. •			; ;	:		:	:		;			:	•		į	:	:	:
1			!!!	:			٠			1		!	!			**			. !		!			!
e de la companya de l	1900							•		1542		11225	•		-					,	Tagage and the same and the sam			
					9=++9				-	1540		8880			1									
:	9.1				- INFLOW FOR LAKE FLOWER DAN				J- 97	1538		is 6725	i	0002+ 05	1548	† †				•				
108	-			•	OR LAKE F		} •		-1528	1534 1536		3065 4775	i	9500 99	1535 1540								•	ı
102 1	•				INFLOW F		N N	~	•	1532 15		1625 30		9160 18466	1530 15						•	-	. •	
16			•		IDROGRAPHS -		NKE FLOWER DAN	*		1531	1550	1010 1	22285	6200 9	1528 1		32	-					<i>:</i>	
11			1.6		CONEIDE 2 HYD		FOUT CVER LAK		٠	1530	1548	200	19290	2800	1525		1.5		•					
*		1.625	-6.10	9	CON	9	10 E	•		1529	1546	. 140	16440	82	1522		2.65			•		,	•	
•	_	**	x -2.0	*	K1	<b>**</b>	K1	<b>&gt;</b>	Y1 1	14 1528	Y+ 15++	Y5 0	75 13755	88	\$£ 1513	\$\$ 1528	\$D 1533		4		•			. •
				1				,	•	:					. •				,				! i	÷
- 26	20'	<b>.</b>	*	) <b>6</b>	93	. 36	56	100	101	102	103	104	105	106	167	104	105	1110	111	112	113	1114	277	
		•				,	؛ ا ا		1			٠.								ì			,	

폱
3
NET
Z
5
2
_

ì

	•			· · · · · · · · · · · · · · · · · · ·	15 42 .0 6	11225.00			i .	••	•			· · · · · · · · · · · · · · · · · · ·			:		· ·	1
	1	. !		· ·	1540-00	8880.00			<b>!</b>	!	•	1/2 PMF		·	;		!		1	1
		IAUTC	•		1538.00	6725.00		!.					12.			•		1962		1 6056
		ISTAGE	LSTR	ISPRAT	00.9	00	+7000.	1545.	١.	•	•			3869	ĺ		2785-			17933
17624 16.16 110.55 154314 150344	:	INAME	-	STCRA -1528.	1536	0 4775	056(	1546.	REA EXPL	: :	1	ES	6	3732	3914	3634	2827	2033.	6298.	17684
329. 10.24. 10.25. 10.	•	1896	IFAP	15x	1534.0	3065.0	18460. 3	1535.	COOL	DANKID 32.	. PAT 10 1	ORD INAT	· «	3354	3935	3667.	2450	2070-	6280.	16984.
60 C R	ROUTING	JPL1	DATA INE 10PT	, × , •	1532.00	1625.00	9160. 18	1530 - 1	ELEVL 0.	АН ОАТА D ЕХРО 7 1.5	PLAN 1	HYDROGRAP		2560.	3956.	3527.	2912. 2491.	2186.		1 5262.
4 N O M W	HYDROGRAPH RO		RES ISANE	LAS APSKK	531.00	1010.00	200. 91	528. 15	EXPU 0.	DAM 2EL CO90 3.0 . 2.7	STATION 600.	END-OF-PERIOD HYDROGRAPP	CUTFLOW	1430	3975	3750.	2553.	2143.	STCRAGE 6247.	12291.
806. 1.048 27.57 14120. 17417.		AKE FLOWER DAY ICOPP IECON 1 0	AV6 16	KSTOL (		72	•	-	C0 05.	1 OPEL 1523.0	STA	END-0	•	511.	3993	3409.	2995.	2181.		9200.
<b>5</b>	•	04EF L ST 40 600	CL055	ASTFS K	1530 +00	19:500-00	2800	. 1525	L SFUID	•	•		**	111.		2445.	2036. 2616.	221£. 185£.		
CES INCLES IN AC-FI THOUS CL M		ROUT	G. 05 S		1529.00 1546.00	140.00	629	1522	CREL 1526.0						,					
		• 1	•	i	1528.00	0.013755.00	•	1513.					•	200						•
	•		:	! !	STAGE 1	FLOM 13	CAPACITY=	ELEVATION=	•	. •				 :		-1 40	r) (V			
• •	•	1		•	20			ų.	•					ı					ı	٠. :

	<b>E</b>	
	60 60 60 60 60 60 60 60 60 60 60 60 60 6	A THE CONTROL OF THE
	2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	100 100 100 100 100 100 100 100 100 100
A	ES 19 19 19 19 19 19 19 19 19 19 19 19 19	2157. 1272. 1272. 226.19. 273.17. 226.19. 24444. 26.34. 26.34. 26.34. 26.34. 26.34. 167.7. 169.31.
10000000000000000000000000000000000000	9 116 2 9 15 1 9 1 9 1 9 1 9 1 9 1 9 1 9 1 9 1	. 6000000000000000000000000000000000000
	4 PLAN 1	9
17 1 1 2 1 2 1 2 1 2 1 2 1 2 1 2 1 2 1 2	ATION 600 -OF-PERIOD H CUIFLOW 9513- 9513- 8065- 7270-	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0
17775. 17087. 16297. 14315. 13495. 1530.0 1534.0 1534.0 1534.0 1534.0 1534.0 1532.0 1532.0 1532.0 1532.0 1532.0 1532.0	END 7. EN	2523. 2642. 1222. 2642. 27033. 27033. 27033. 2703. 2703. 2703. 2703.
11111111111111111111111111111111111111		
	2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	4620. 1856. 7159. 29147. 29147. 29147. 29147. 21878. 19984. 19984.
173 173 173 173 173 173 173 173 173 173	96 6 4 2 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4	5806- 5906- 52163- 28163- 28163- 28243- 28564-
M OUTFICE		

	•					247703	APPITER 1	300 61 010			
OP BRATION	STAJION	ANEA	-	RATIO 1	AATIO 2						į. 1
HOROGRAPH AT		32.90	1	10003.	20007.	•• .•	t				ì
MOLTED TO	200	12.96	1	10003.	20007.			1	; ;	1	: :
HORCGRAPH AT	281	41.56	:	15624.	31248.	••					
2 COMBINED	<b>88</b>	74.46	<b>4</b>	25628. 725.69) (	51255.	<b>6</b> (16)				•	
MOUTED TO	280	74.40		2862. 81.05)(	6454.	g de swe			1 1	f	i
MOUTED TO	300	17.40	7	2862. 61.05)(	6454.	· • • •	t .	, 1 :	.,		
PTCRCGRAPH AT	35	24.00	7	9456.	18912.	•	:	•		ř	;
· 2 COMBINED		16.40	-	10393.	21558.	en grand	•		:		•
OJ OJINON	38	98.40	-	2466.	5356.	••••	· · ·	i :	1	,	•
01 031700		19.40		2466.	5356.			į	; ;	:	:
W DRCGRAPH AT		23.70		10471.	20941.	;					
WORGGRAPH AT	38	19.20		6950. 196.79) (	13899.	• .				i	
3 CGROINED		141.30		17900.	36140.		. ,	1	•		;
MOUTED TO		141.30	1	3178.	7185.	, <b>-</b>	•	•		*	!
MOETED TO	<b>3</b> ;	141.30		3178.	7185.				:	i i	. :
WERCGRAPH AT	5	27.60	-	14202.	28464.		•			į	
2 COPRINED	***	•••••	•	,							

\*\*\*

2 COMBINED PRO		1796A	•	:				,					٠.	•
_	•	<b></b>	<b>3</b> 1	1(84.74)	925.3816	- <b>1</b>	!		:	•				•
POLIED TO 680		179.10		. • 1	9638. 272.9216				: : :	· .				•
	<u>.</u>		7	1	U	•	! !			! !	t t			•
			<b>%</b>	E E			•							.•
	;		· •							ï				
	į	1	;	:.	•						; ;			
			i i	1	· !	1				ł ;				•
•••  •••			i	:	i	,		, *	:			•		
•	1	i i	• •				,	•	;	•			•	,
•	1	l ţ	í	•		<b>^</b> .	· .			:	:		•.	
1	1		i	<b>.</b>		e estas		,	:	:			•	
	<u>.</u>	i i		· !			,	i	1	•				
							i i		; ;	•				•
	1	•	1			•						•	•	
!	i	i .	i -	•		···· .	. •	i <b>i</b>					•	į
							r	and the second	1	i i		٠		
1	1	:   •	i			•		1	;	•				
	ļ	; ;	ί	,		•					;			يار
		i -   i		,		• .	í,			! !				•
i (	1	•.				•	ı			1	:			
	1	i i	1	;							• !			i
	,	í	i		•	•								
					•			i	1	1		•		
	1	1	`.   	! ;								4		
• 1	į	•	:	,				i !			•			•
								•	ı					
	All and the second	The state of the s			•			·					•	•

The state of the s

And the second second

tQ-

0

U


3	•	
MIDDLE SARANAC LAKE		
₩ .		
MODE	TITE OF FAILURE ECES G.	
	· •	
10P OF DAN 1540.00 6000. 742.	TINE OF MAX GUIFLON HOURS 1114-C0 117-C0	
844		
	DURATION OVER TOF HOURS 255.60 258.60	
55		
SPILLMAY CREST 1536.00	MAXINUM CUIFLOW CFS 2466. 5356.	
TALUE 10 10	CAX TRUB STURAGE AC-FT 19164.	
INI TI AL VALUE 1516.00	MAXIMUM DEPTH OVER DAM 4.54 9.99	
8		
ELEVATE STCRAGE GUTFLES	PAXINUP RESCROIR B.S.ELEV 1544-54 1545-54	
	_	
	2000	
	•	
-	1	
į I		
! .!	! !	
!		

•	y	3
OTH BT		LOWER SA
	The second secon	
	:	
	!	
YSIS		
ANAL		
SUMMARY OF DAM SAFETY ANALYSIS		
MYOU		
5 -		
SUFFAR		
	!	
	{	
	!	
	ŀ	
	1 1 1 1 1 1 1 1 1 1 1	
	İ	
	İ	

SARANAC LAKE	
LOWER	TIPE OF FAILURE ACLRS
1537.48 1537.48 8571. 1688.	TIME OF MAX OUTFLOW MOURS 108.68
i !	DURATION OVER TOP NOURS 216.00
SPILLWAY CREST 1533.00	MAXIMUM CUTFLOM CFS 317 E. 7185.
4ALUE 6.00	MAXINUM STORAGE AC-FT 12860. 24265.
18:35.00 15:35.00 0.	MAXINUM DEPTH OVER DAN 2-00 6-07
ELEVATICE STCRAGE CUTFICE	RAKINUP RESERVOIR Vass Effe Mass of Mass of
	7A710 007 7NF 0.56 1.067
PLAN 1	
•	1 1


LA!	Αli	N	٨	۸ıı	.L	ſ	A	Μ											SH	) (3	yo.			CHI	ECK	D C	Y		DA.	rE			
ULLEC	έT										_		-			_	<del></del> -		<b>!</b>	7	_			CO	MPU		BY		DA'			181	_
W			<u> </u>			<del>_</del>	TAK	T T	1ET		<u>5</u>	1	1	<u> </u>	ì	Γ-	_	Τ_	_	Ė	<del>-</del>		Γ	$\vdash$	$\frac{\omega}{1}$	-	Τ	Г	╁	<u>//°</u>		<u> </u>	_
5	B	BA	51	1		ħ	<b>b</b>	E	R	:	T	T		忊		一	$\vdash$		┢			一											
$oxed{\Box}$			L																														
<u> </u>	۲۰۱	Œ	R	L	U	717		44	D	2	S	ŁΔ	P	Ŀ	L	L	L		L	L	L	L	L	<u>L</u>	<u> </u>	L	<u> </u>	_	L	_	_	L	L
+-	<u> </u>	L	L	L	L	L	L	<del> </del>	Ļ	├-	Ļ	Ļ	L	Ļ	ļ	Ļ	_	<u>b.</u>	3	ļ	_	_	ļ	ļ	ļ	_	-	_	├	<u>:</u>	<b> </b>	⊢	<u> </u>
+-	-	اح	┦	M	Æ	•	┝	╀	牛	-	=	10	F	۲	×	1	LA.	<del>)</del>	-	-	_	-	-	┝	├	┢	├		┢	┝	┝	H	┝
†	┢		卜	$\vdash$		┢	t	┢	十	$\vdash$	$\vdash$	5		F.	2	. 0	-	-	┝		54		5	H	-	_	-	1	3.	75		H	1
1	Г		Г	一	┢	T	T	1	T	$\vdash$		٢	E	Ħ		-		<del>                                     </del>		-		-	7			7	<b>~</b>						T
									Ł		3	19	.0	9	н	15																	
			L					$oxed{\Box}$	١٩																								
4-	_	L	ļ.,	L.	<u> </u>	_	L	L	_	L	_	L		L	_	Ļ	L		<u>.                                    </u>		L			<u> </u> _	_	<u> </u>	_	Ĺ			_	_	L
+	77	717	R	Αı	NF	A	1	1	)B	ΑŢ	70	H	<u> :</u>	<u> </u>	<del> </del>	t.	2	_	ŧ,		<b> </b>		<u> </u>	H	_		<u> </u>		H	$\vdash$	<u> </u>	<u> </u>	<b> </b>
+-	-	$\vdash$	├-	├-	┝		-	┢	$\vdash$	├	├	<del> </del>	-	-	├-	<del>  '</del>	-	5	.5	H	-	$\vdash$		$\vdash$	<del> </del>	$\vdash$	-	-	-	$\vdash$		$\vdash$	<b> </b> -
+	-	-	┝	-	┝	-	$\vdash$	┝	E	-	-	-4	-	<u> </u>	l S	-	-	┝	┝		_	H	-	H	┝	1,1	-	┢	ŧ	-	7	HS	-
†			H	-		-	┢	┢	r	-	-3	-9	1	7	2	<del> -</del>	-	$\vdash$	┝		$\vdash$	Н	-	-	-	"	ÞΕ	$\vdash$	ħ	r	3	111	12
11				Т		$\vdash$	Т	T		$\vdash$		一	$\vdash$	H	H	┢					┢	Н							$\vdash$	М	М		┞
	AD	טט	51	Εſ		L	AG		71	ME	:			m	٠.	ŧ		+	a	. 2	5/	ŧ	•	+	7								
								Ľ									P				_	Ŗ			77								
						L																											
4-1	_		<u> </u>				<u> </u>	<u> </u>	T <sub>C</sub>	=	<u> </u>	19	09	+	٥	ಎ	5(	3	-	3	٠.4	7)					_						Ļ.
+-1	_	Н	<u> </u>		L	_	-	-	L	L	<u> </u>	_	-		_	_		<u> </u>			_		_	_	_	_	_				_	H	<b> </b> -
╁┤	$\vdash$	$\vdash$	-	<u> </u>	H	├	H	-	Ш	=	-	18	.9	7	116	5		-	$\vdash$		_	Н	_	Н	_	7	E	$\vdash$	Tr.	=	13	HB	3
+	H		Н	Η	-		$\vdash$	-	┢	$\vdash$						-	Н		Н			Н		H				Н	Н				-
	OF	Ä	1	6		CC	E	E	cı	: N	+	:		CF		$\vdash$			H		_	H		$\overline{}$			Н		Н	П	H	H	一
$\top$				1				Η,			+	r						Т				Н		П		- C	OR	8	Ę	Š	2	_	-
		Į.	8	7	A	4	2	Ð.	E	13	AT	ΞP	3	E	5	:								RE	F		PP			120	1	_	E
																										M	đ	À	V	RI	Á	2	ا بر
$\downarrow$	Ш	Ш	Ц	Щ	•	υê	BA	21	2		34	Ц		2	وا	3	9	.5	5							Ŀ	4	7		5	פנו	7	
44		Н	Н	_			20	ļ	_		_	Щ	_		_	<u> </u>	L					Н		Щ		_			Щ			Ĺ	L
+	$\vdash$	Н		_			-	<del> </del>	$\vdash$		38	Н		4	9	-	9	.5	4	-	Щ	Н		Н	Н				Į	닑		Н	Ŀ
+			Н	Н	Н	Н	$\vdash$	┝	$\vdash$	Н	Н	Н		$\vdash$	Н	-		Н	Н		Н	Н	Н	Н	Н	Y	Ц		4	띡	믝	K	9
++	Н		Н	Н	Н	Н	$\vdash$	-	H	_		H		Н	Н	$\vdash$	Н	-	Н	-	-	H	_	-	Н	$\vdash$	Н	-	Н	$\dashv$	$\dashv$	$\vdash$	-
11	H	Н	H	Н	Н	Н			Н	Н		H		Н	H	$\vdash$	H	H	H	Н		H	$\dashv$	$\exists$	H	$\vdash$	H		H	$\dashv$	$\dashv$	$\vdash$	۲
T	П		П	П		П			П	Π		П			П		Н					Н			П		$\exists$		H	$\dashv$	$\sqcap$	М	-
$\Box$		٠																															
$\downarrow \downarrow$	Щ		Щ	Ш	Ц	Ц	Щ	L.	Ц		Щ			L		Ц			Ш			Ц							Ц		Ш	Ц	
╀┤	Н	Щ	Н	Щ	Щ	Щ	H	<u> </u>	Н	Щ		Щ	Щ		Щ	Щ	Щ	Щ	Щ	Щ	Ь.,	Ц		Ц	Ш							Ш	_
		1	l i	l i				l		ı	l					1 1	1	1 1	1	1		1		1	ıi	1			i !	, 1	. !	1	Ī

MAIN MILL DAM  SUBJECT  WATERSHED PARAMETERS  WILL  RAINEALL INSELERATION - SOIL LOSS RATES I  WATERSHIP INSELERATION - SOIL LOSS RATES I  WATER BOOK - LAS - LAS - REF: WATER BOOK - SOID AND AND STRAFTO - REAL WATERSHIP STORY  THATTO - REAL CASE CASE (GAVES - CASE DATA) - LAT CEMP  Q - BER CAS (GAVES - CASE DATA) - LAT CEMP  QQ - BER CAS (GAVES - CASE DATA) - LAT CEMP  QQ - BER CAS (GAVES - CASE DATA) - LAT CEMP  RAINEALL - HARRESTSS:  RAINEALL - HARRESTSS:  ADDUST HENT FOR MAINEAUTION  ADDUST HENT FOR M	<b>J</b> 0		۱A	IN		<del>-</del> ۷،		•	DA	M	<del>, -</del> -					_					8+1	3				СН	CKE	D B	<b>y</b>		DA	ΓĒ			
RAINFALL INTELERRATION - SOIL LOSS RATES :  (MITTIAL LOSS = 1. D INS. CONSTANT LOSS = QIO INDAIR  RAINFALL DOSS = 1. D INS. CONSTANT LOSS = QIO INDAIR  RAINFAL LOSS = 1. D INS. CONSTANT LOSS = QIO INDAIR  RAINFAL LOSS = 1. D INS. CONSTANT LOSS = QIO INDAIR  RAINFALL STORY  RAINFALL - HRR = 32 :  R	90		T								· AA		E D	_												CO			BY		DAT	re 7/:	23	/ <u>a</u>	
RASE FLOWS = 1.0 INS. CONSTANT LOSS = Q.IQ INS/AR  BASE FLOWS  RTICK = 1.5		$\Box$		J.					Ľ	ľ		<u>-</u> 7			Π											_	$ ilde{\square}$						$\tilde{\Box}$	Ĭ	
RASE FLOWS = 1.0 INS. CONSTANT LOSS = Q.IQ INS/AR  BASE FLOWS  RTICK = 1.5								L	lacksquare			L																							
PASE TROUDS  RITIOR = 1.3  STARTO = RER CFE  AVE Q = RES CFE  Q = RER CFE  Q = RER CFE  AVE Q = RER CFE  RIVER 448A51)  QCC SN1 = 0.0  RAILER 1	-	RA	N	E	4	$\vdash$	Ŋ	ŧĽ	TR	<b>A</b>	10	M	=	۽	61	-	_	O'	25		84	IE	5	1	Н	-	Н		_		Н		H		$\vdash$
PASE TROUDS  RITIOR = 1.3  STARTO = RER CFE  AVE Q = RES CFE  Q = RER CFE  Q = RER CFE  AVE Q = RER CFE  RIVER 448A51)  QCC SN1 = 0.0  RAILER 1		$\vdash$			┢	┢	IMI	1		1	be	5	-	1	<b>b</b>	,,,	5	$\vdash$	-		6			AN	H	10	1	. 3	d	10		12	5/	.2	
RTINOR = 1.3 - REF: UPP EN 400 300 F NO HANK  RTINOR = 1.3 - REF: UPP EN 400 300 F NO HANK  RIVER GENTAL STUDY  AVE G = 835 C/S (G 3 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4																																			
RTINOR = 1.3 - REF: UPP EN 400 300 F NO HANK  RTINOR = 1.3 - REF: UPP EN 400 300 F NO HANK  RIVER GENTAL STUDY  AVE G = 835 C/S (G 3 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4	_	L			L	┞	L	_	_	├_	_	<u> </u>	<b> </b> _	Ŀ	L						_	_	_	ļ.,		L	Ц			_			Н		
RTIOR = 1.3 - REF: UPPER HUDSON F MOHANG RIVER SASIN STORY  STARTO = SER CFS  AVE Q = 835 CFS (G 3 CSM - LOVER 4 MASSIN)  QCC SN1 = 0.0  RALLEALL - HERR # 33:  ADUIST MENT FOR  ADUIST MENT FOR  ARE : UPPER HUDSON F MOHANG RIVER SASIN STORY  RALLEAL - DIRECTOR  ARE : UPPER HUDSON F MOHANG RIVER SASIN  STORY  ARE : UPPER HUDSON F MOHANG RIVER SASIN  ROLLEAL - GAGE DATA ) - 1.37 CSM  RALLEAL - HERR # 33:  ARE : UPPER HUDSON F MOHANG RIVER SASIN  ARE : UPPER HUDSON F MOHANG RIVER SASIN  RIVER SASIN  RIVER SASIN  STORY  ARE : UPPER HUDSON F MOHANG RIVER SASIN  RIVER SASIN  STORY  ARE : UPPER HUDSON F MOHANG RIVER SASIN  ARE : UPPER HUDSON F MOHANG RIVER SASIN  RIVER SASIN  ROLLEAL STORY  ROLL	$\vdash$	BA	55		P	þ	<u>) :</u>	-	╁	╁	┢	-	┝	<b> </b>	╀	$\vdash$	-	-	$\vdash$	-	$\vdash$	-	┝			<u>_</u>	-	V		-	_	Н	Н	$\vdash$	$\vdash$
RAIL FALL - HRR # 33:  RAIL FALL - HRR # 33:  AD UIST MENT FOR  AD UIST MENT FOR  ALEA - DURATION  AND SOR ARE STORY  ARE STORY  AND SOR ARE STORY  AND SOR ARE STORY  AND SOR ARE STORY				R	10	R	=	1.	3						$\vdash$		$\vdash$	4			RE	F:									٤	] 9	A	ЭK	
AVIE Q = $925 \text{ c.f.}$ (G $3445 + 6466 \text{ Data}$ ) -> $1.37 \text{ c.s.m}$ QC $541 = 0.0$ RAWEALL + HRR = $33:$ $300 = 941 / 24 \text{ Hr}$ (M $350 = 16$ )  AD (UST ME UT FOR AREA - DURATION)  AS (UST ME UT FOR AREA - DURATION)																															<u>-</u> S	ប្រ	Ş.		
RANDEALL - HRR # 33:  2015 1 300 SQ MI / 24 HR INDEX MM = 16  AD 11) ST ME UT FOR  AREA - DURATION 1	-	ļ.,		2	Δſ	4	8	3	ļ	85	8	عـا	<b>f</b> ≘	<u> </u>	<u> </u>		<u> </u> _	<b> </b> _	_		L	_	_	<b> </b> _		<u> </u>	Н		$\vdash$		H	_			
RANDEALL - HRR # 33:  2015 1 300 SQ MI / 24 HR INDEX MM = 16  AD 11) ST ME UT FOR  AREA - DURATION 1	-	-	-	-	$\vdash$	A.			╁	<del> -</del>	-	3.5	<del> </del>	Ce	$\vdash$	<b> </b> -	/-		ے			-	<u> </u>	64		7			-	27		3	Н		H
RAILEALL - HRR # 33:  RAILEALL - HRR # 33:  ADUISTMENT FOR DURATION  ADUIT FOR DU																Y									1	1									
RAILEALL - HRR # 33:  RAILEALL - HRR # 33:  ADJUSTMENT FOR  AREA - DIRATION  10 10 10 10 10 10 10 10 10 10 10 10 10 1								Q		=	8	58	ع	£		Ø	1	<b>c</b> 1	Ð			ď	E	٤	Ę	À	31								
RAILFALL - HRR # 33:  RAILFALL - HRR # 33:  AD JUST ME UT FOR  AREA - DURATION  O 10 00 00 00 00 00 00 00 00 00 00 00 00	-	-				_		-	├	<del> </del>	_	-	-	-	-		$\vdash$	-	$\vdash$		H	<u> </u>	-	-	Н		Н	_		_	-	_		$\vdash$	H
2015 1 300 SO MI / 24 HR M DE ( PM = 16)  AD JUST MEUT FOR TOWN TOWN TO A STATE OF THE STATE OF	$\vdash$			7		P	1	-	┢	P.		-	$\vdash$	┝	-	H	┝	-	Н	Н		┝	╁	┝	Н	_	Н		-		Н	Н	H	Н	-
SCALE 1 300 SO MI / 24 MR MADEX PARE 16.																																			
2015 1 300 SO MI / 24 HR M DE ( PM = 16)  AD JUST MEUT FOR TOWN TOWN TO A STATE OF THE STATE OF																																			
2015 1 300 SO MI / 24 HR M DE ( PM = 16)  AD JUST MEUT FOR TOWN TOWN TO A STATE OF THE STATE OF	-	-	Н	_	<b> </b>	_	_	┞	_	-	_	_	-	-	_			-	_	Н		-	-	_	Н	_	Н			H	Н		$\vdash$	$\vdash$	
2015 1 300 SO MI / 24 HR M DE ( PM = 16)  AD JUST MEUT FOR TOWN TOWN TO A STATE OF THE STATE OF	-	R A	1	E		-	-	┢	υ¢	Q	#	22	•	-	$\vdash$	$\vdash$		-	$\vdash$				-	-	Н	-	Н		Н	Н	Н		H	$\vdash$	Н
AD JUST MEUT FOR JUST MEUT SAS AS																																			
AD LUST MENT FOR AREA - DURATION				ZC	NE		1			a	8	S	<del>o</del>		2	4	HR		E L	H	L	A	¥	•											
	┝		Н	H	┝	H		_	L	_		-		_	-	ш	H	H	Н		Н		-	_	Н	Ļ	$\dashv$			Н	Н		Н	$\dashv$	
	-		Н	-	$\vdash$	H	AP	100	Ħ	ME	77					9			5	H	Н	-		$\vdash$	Н	Н	H	$\dashv$		Н	Н				
																	į	j			13				6				4						
	H		Н		-	$\vdash$	$\vdash$	<u> </u>	├-	-	%	٩	<b>F</b> _	W	2	۴	59	$\vdash$	$\vdash$	1	4.	3	-	Н	- 6	$\vdash$	$\dashv$	$\dashv$	3	Н	Н		Н	$\dashv$	Н
	H		Н	-		$\vdash$	$\vdash$	H				<del>                                     </del>	_	Н		$\vdash$	-				Н		H	$\vdash$		Н			Н	H	$\vdash$	Н	H		
			П													П												$\Box$							
	-	$\vdash$	Н	_	_	H	_	_			$\vdash$	$\vdash$	$\vdash$	Н		Н	_	H	$\vdash$	Н	Н		H	Н	Н	Н	$\dashv$	-		$\vdash$	$\vdash$	Н	Н	$\dashv$	Н
	-	H	Н	-	-	H		-	$\vdash$	-	H	$\vdash$	H	$\vdash$	┝╌	Н	-	Н	H		Н			Н	Н	Н	$\vdash$	$\dashv$			$\vdash$		H	$\dashv$	Н
	-		$\vdash$		<u> </u>	H		<u> </u>	<u> </u>	-	_	<u> </u>	$\vdash$		<u> </u>	Щ	lacksquare	$\vdash$		Ц	Н	Н	-	$\vdash$	H	_	$\vdash \downarrow$	-	_		Н		Н	$\dashv$	Н
	-	-	$\vdash$	-	-	-	$\vdash$	-	-	$\vdash$		_	$\vdash$	Н		Н		Н	Н	Н	H	H		Н	$\dashv$	Н	$\dashv$	ᅱ		$\vdash$	Н	Н	$\vdash$	$\vdash$	H



[2	08 M	۸۱	. 1		м	11	,		٠	<u></u>	W												ET I	yo.			CHE	CK	0 6	Y		DA	nE.			
s	ÜŅE	CT																	<del>.</del>			<u> </u>	5/				CON		TED	BY		DAT	TE ,		_	;
				_(	J.P	77	_	_1	D١٩	50	H	AR	G	3								_						ω	L				<u>7/6</u>	94	/8	_
L		┵			L	Ľ	1	$\downarrow$				L		L	L				L										L	L	_		<u> </u>		Ц	L
<u> </u>	4	1	4		L	L	1	4	_	L	L	1_	L		L	12	<u>k</u>	igspace	L.	L	Ц		L	L.		Ш			_	<u> </u>	_				Щ	L
<b>-</b>	-μ	ŧ	7	<u>_</u>	E	4	علا	4	:	ļ	L	P	Ξ	C	لها	<b>A</b>	۲	_	<u> </u>	L	Ш	_								<u> </u>	├-		_	-		L
$\vdash$	+	+	4		<u> </u>	┞	+	4	_	_	┞_		-	_	Ļ.	ļ.,	L	↓_	▙	┞-	$\square$		<b>L</b>	ا استون	_		Н	_	-	ļ		$\vdash$		-	Н	L
H	+	+	١d	_	EL	A:	#	ß	2	87	2	ļ	<b> </b> _	<u>C</u>		3.			-	-	_		<u> </u>		<b>—</b>	Н		_		L	-				H	L
-	4-	╄	4		⊢	╀	+	4		H	├-	₽-	┞	1	3	2	5	<b>-</b>	₩.	ļ.	Н	Щ	Н	<u> </u>	H	$\vdash$		_		├-	-	H			Н	H
_	+	╄	4	_	┝	┡	╀	4	_	_	<b> </b>	┡	<u> </u>	_	-	<del> </del>	┝	├-	├	₩	1	•	<b>H</b> -	4.	<del>})</del>	Н	$\vdash$		$\vdash$	├	-	$\vdash$			Н	┝
⊢	+5	4	4	Υ_	<del> </del>	╄	+	4	H	<u> </u>	├	<b>├</b>	3	щ		#	├-	⊢	┢╾			Н	Н	⊢	Н	Н		_		├	-	H	I	Ā	ΑL	┝
	+	╁	+		-	╀	┿	+			┞	<b>├</b>	╀	Q	┞	┝	┝	┼	┝	┝	4	Н	-	-	1	Н	-		Q	┝	-			0	Н	H
CREST	┿	18	4		┝	┝	┿	7	Ξ	È	├-	╂┈	-	F	-	-	├-	╀	┝	-	$\vdash$	Н	$\vdash$	┝	-	Н		_	-	┝	╂─	Н	-	Н	H	۲
 	+	+	+		-	╁╴	╁	┧	ᆜ	-	├	┝	-	_	┢	+-	┢	╁	├-	$\vdash$	$\vdash$	┝╌	$\vdash$	┝	$\vdash$	Н	Н	_	-	-	-	H		Н	Н	۲
H	+	+	+		۲	$\vdash$	+	4	.5		╁	╁	لقا	54	-	┢	+	$\vdash$	$\vdash$	╁	Н	H			-	Н	H	۳,	-	┝	$\vdash$	H	H		H	H
  -	+	t	┪	-	H	┢	+	+	,	<del> </del>	╁	╁	-	20	-	$\vdash$	┢	-		$\vdash$		-	$\vdash$	┝	$\vdash$	Н	$\dashv$	-	-	-			$\vdash$	Н	H	┝
	+	t	+		$\vdash$	H	$\dagger$	+	씸	Н	<del>                                     </del>	1	+	كانم	1	╁	<del> -</del>	├	$\vdash$	+-	$\vdash$		H	$\vdash$		H	H			1		H		H	H	┝
<b> </b>	+	†	+		$\vdash$	H	+	╗	.5		1	$\vdash$	17	26	-	$\vdash$	十	十	-	+	Н	-	Н	Н	$\vdash$	Н	Н			-			М	Н	Н	H
_ F	+	t	7		-	H	十	7	•		_	H	113		-	H	┢	f	┢╌	Н	H					Н				$\vdash$	1				Н	┝
<b> </b>	十	Ť	+		Г	T	十	7	a	Н	_	T	5	34	<u> </u>	T	t	T	T		Н		П			Н	$\vdash$			<u> </u>	Г		Μ		П	Γ
	十	t	7		Г	1	t	7	•			T		~		$\vdash$	1		1	Г	П									Т				Н		Г
TOP	十	t	1	_	Г	Г	1	a	.5		Г	<u> </u>	28	Ma		T	<u> </u>		┢		П			П	П			_		Г						Г
CARRE	T	1	7			T	T	٦																												
	1	T	1			Τ	1	1	3				37	41		Г																				Г
Г	T	Τ	7			Γ	Τ	7			Γ	Г	Γ				Γ																			
	$\top$	T	1			Г	T	1	4			Г	57	60			Γ	T																		
_E	I	Ι						I																												
TOP	$oxed{T}$	Ι					L	4	.3				64	$\infty$																						
	$\mathbf{I}$	I	$\Box$									L											J	.11	<b>ી</b>	GZ	·									
		$\mathbf{I}$	$\prod$				L	4	В				75	71						_		1	٦		10			_						75	71	
E			$\rfloor$																																	
	$\perp$	I							5			L	80	49				L		ع	.2								a					8	51	
		Ţ	1			L	Ţ					匚	L			L	L	L		L					Щ											L
L	┸	1	1			L	┸	4	6			_\	05	97	_	L	L	L	L.	Ц	<u>.</u>	Щ			Ц				34	_		Ц	L	ď	15	
L	1	╀	4		Ц	L	┸	4	_		L	L	_	L	_	L	L	L	L	L	Щ				1				Ц	_	Ш	Ц	Ш			L
<b>—</b>	4	1	4			L	╀	4	7		L	ш	33	34	<u>-</u>	ļ	<u> </u>	<b>L</b>	L	2	۵.	_	_		<u></u>		_		25	_	H	Ш	لا	34	13	_
<b>-</b> -	4	╀	4		_	L	╀	4	_		L	L	_	L	<u> </u>	_	<u>_</u>	<u> </u>	<u> </u>						Щ		_					Щ	Щ			Ļ
TOP	4	╀	4		L	<b> </b> _	Ļ	4	8		-	Ш	5/4	84	<u> </u>	<u> </u>	<u> </u>	₋	<u> </u>	<u> </u>	3		Щ	_	Ц	$\sqcup$	_	_	3/6		Н	Н	Щ	83	30	L
<b> </b>	+	+	4	_	$\vdash$	↓_	╀	4	ᆜ	Щ	<u> </u>		_	Ļ	<u> </u>	<u> </u>	<b> </b>	├-	<u> </u>	_	Ц	Н			Н	Щ	$\dashv$		Ы		Н	Н		Н		ļ.,
<b> </b>	+	+	4		<u> </u>	┞	+	4	ಶಿ		<del> </del>	Ш	هَمَا	91	-	-	<b> -</b> -	-		13	9	Щ	H		Щ	Н		_	50	_	Н	Н	_4	64	41	L
<b> </b>	+	+	4	_	<u> </u>	┞	+	4	إ		-	-	<u> </u>	-	<u> </u>	-	}_	-	<b> </b> -	-		Щ	Н	Н	Н	Н			Н	H	Н	Н	-			-
-	+	╀	4	-	<b> -</b>	┡	╀	+	و		-	${f H}$	94	40	┡	├	-	├-	-	4	ء.		$\vdash$		Н	Н	$\dashv$	2.	2/	Н	Н	Н	_4	96		<u> </u>
<b>-</b>	+	+	4	_	<del> </del> -	-	+	+	-		⊢	-		_	-	-	-	├-	-	-		Н	Н	_	H	$\dashv$		_	4		Н	Н	_			-
  -	┿	+	+	_	H	+	+	9	-4		-	Н	97	144	┝	┝	┝	$\vdash$	-	19	.3	H	Н	Н	Н	Н	$\dashv$	لف	34		Н	Н	-4	8	76	-
1080 1000	+	╁	+		<del> </del>	┝	+	╁	亅	H	-	Ļ	20	00	┝	┝	-	╁	-	┝	5	Н	H	щ	Н	$\dashv$	-	_	3	ш	Н	H		35		┝
MOONIL	4-	L	_1		L	1	.1	S.	8		l	اما	Z)		L	L	L.	1	L . i	L	121								·			ш	الف	-2		_


1	JOI		A	N		MI			D	Ą٧	١				-						SH	G/				CHE	CKE	D B	Y		DA	TE.			
	SUI	JEC	Ť			-						50	<u> </u>	Α	RG	Έ	5		·	•	<b>-</b>					COI	W)		BY		DAT	re 7/2	4/	<u>'81</u>	
						_	_	Ļ	_	L	L	_	_	<u> </u>	L	H		-	<u> </u>	<u> </u>	L	_	<u> </u>	<u> </u>				_	-	-	_		$\vdash$		
	Н	OR	1	2	E.	F	9	$\mathbf{\omega}$	=	$\vdash$	_	Q	=	2	A.	И	Pg	H	-	H	-		$\vdash$	_	Н	-		_	├-	┢	$\vdash$			$\dashv$	
					$\vdash$			┝	-	-	┝	-	┝	7	늘	┝	-6	-		<del> </del>	┢	$\vdash$	$\vdash$	_	-	Н	-	_	┝╴	$\vdash$	-				_
				H		E			2	۴E	7		┪		3			╁	=	1	<u></u>	×	ıa				_			Г			П		
			_	0/	G					70		6	s	611	ıc	RE	51	7	_			86													
				1	_	Ľ			_									_																	
			9	Ħ	51	<b>Z</b> _	8	Н		L	L		L	H	-	4	EA	ناط	RE	<u>b</u>	뒫	24	_	ELi	Ŋ.	18	0	_	_	_	L				
	Щ	Ш	_	_	_	_	L	·	<u> </u>	<b>L</b>	_	L	<u> </u>	L	<u> </u>	Ļ	ļ.,	ļ	ļ.,	<u> </u>	L		_	ļ	_	_	_	-	_	L	<u> </u>		Н		<u> </u>
	Н	트	LE	٧_	-	-	-	H	$\vdash$	$\vdash$	$\vdash$	-	Q	$\vdash$	_	<b> </b>	-	$\vdash$	-	-	-	-	⊢	_	$\vdash$	$\vdash$	-	$\vdash$	-	-	$\vdash$	Н	$\vdash \vdash$	$\vdash\vdash$	_
	-	닉	86	<u> </u>	-	$\vdash$	$\vdash$	6	-	-	$\vdash$	-		15	-	-	$\vdash$	+-	-	-	-	-	_	-	-	$\vdash$	H	-	-	-	<del>                                     </del>	Н	H	$\vdash$	-
CREST	Н	Н	Zα	-		<del>                                     </del>	$\vdash$	9	-	$\vdash$	<del> -</del>	-	14	12	<u> </u>	1	$\vdash$	$\vdash$		$\vdash$	$\vdash$	$\vdash$	-	$\vdash$	-	_	$\vdash$	_	<del>                                     </del>		-		H	$\vdash$	$\vdash$
	Н	H		_			10	.5					14	73	$\vdash$	H		1		$\vdash$	T	Ħ							$\vdash$				$\sqcap$		$\vdash$
																T																			
								7					15	28																					
																	L		L		L		_						L	L			Ш		
			Щ		<u> </u>	_	7	.5	_	_	L	_	15	82	<u> </u>	_	L	L	_		ļ		_		_			L.	_	_	_		Ш		<u> </u>
		Щ	_	L	_	L	<u> </u>	_		L	L	-	<u> </u>	_	_	<b> </b> _	┡	ļ.,	_	L	Ļ.	_		_	_			L	_	_	L	_	$\vdash \vdash$		┡
		Н			-	<u> </u>	-	8	┝		┢	-	16	34	-	┢	╀	├		⊢	⊢	-		-	-	_	-	-	-	-	-		Н	_	<del> </del>
	H		-	-	├	-	١.	.5		H	<del> </del>	├-	.,	84	┝	┢	╁	+-	$\vdash$	$\vdash$	┢	-	┝	-	-		-	┢	┝	┢	$\vdash$		H	$\vdash$	┝
	Н			-			٩	3			$\vdash$	$\vdash$	140	<b>D</b> 4	H	-	+	1	$\vdash$		H		$\vdash$	-	-	-	-	$\vdash$	┢	-			М		$\vdash$
			_		T			9		Г	┢	<u> </u>	17	33				1			T	Г								Г			П		
								0					18	27			$oxed{oxed}$														L				
					L	L		L	L	L	L	L	L	L	L	L	L	_	_	L	L		L	L_					L	L	L		Щ		_
	Щ	Ш		L	_	<b> </b>	Ш	þ.	3	<u> </u>	<u> </u>	<b> </b>	8	54	<u> </u>	<u>L</u>	-	$\vdash$	_	<u> </u>			_	_	<u> </u>	_	_	_	<del> -</del> -	_	<u> </u>	$\sqcup$	$\mid \perp \mid$		<u> </u>
	Н	Н	Щ	H	_	-	$\vdash$	_	-	$\vdash$	┡	_	<u>_</u>	<u>_</u>	<u> </u>	┡	+	╄	├-	<u> </u>	-	-	-	_	-	⊢		_	<b> </b> -	$\vdash$	-	Н	$\vdash$		-
		H	<b>-</b> -	├	├-	<del> </del>	Н	ο.	18	-	<del> </del>	-	18	98	-	┝	╁	╁	$\vdash$	$\vdash$	╁	┝	<del> </del>	╁	-	-		-	<del> </del>	-	-	Н	$\vdash\vdash$		-
	H	${\mathbb H}$	-	$\vdash$	-	$\vdash$	$\vdash$	n	$\vdash$	1	$\vdash$	1	10	16		<del> </del>	T	十	$\vdash$	$\vdash$	t	$\vdash$	-	$\vdash$	-	Н	$\vdash$		<del> </del>	┢	$\vdash$	Н	H	$\vdash$	H
	Н			$\vdash$	T		1	٣	T		T		<del>   </del>	1	Т	T	T		$\vdash$		T	Т							Г		П		М		1
								ເລ					20	OI			Γ																		
								13					<b>3</b> C	83	L	L	$oxed{oxed}$	L	L	_	L		L	<u> </u>					_	L	_	Щ	Ц		
TOP	L	Щ		<u> </u>	L	L	<u> </u>	L	_	<u> </u>	_	Ŀ	_	_	<u> </u>	L	↓_	$\vdash$	_	<u> </u>	L	_	_	<u> </u>	_	_	_		<u> </u>	<u> </u>	_		$\vdash \dashv$	<u> </u>	<u> </u>
EMB	Ц	Щ		<u> </u>	_	-	Н	3	8	$\vdash$	_	-	51	46	<b> </b>	L	╀	┼-	⊢	-	┞	-	⊢	-	-	ļ		H	-	<u> </u>	_	_	$\vdash$	-	
	Н	$\vdash$	_	<u> </u>	-	-	-	-	-	-	-	}_	┝	⊢	-	┝	╁	╀	⊢	$\vdash$	╀	-	├	-	_	-		H	-	-	$\vdash$	-	$\vdash$		┝
	Н	Н	-	┝	┝	$\vdash$	$\vdash$	-	$\vdash$	-	$\vdash$	-	-	$\vdash$	+	┝	$\vdash$	╁╴	$\vdash$	$\vdash$	$\vdash$	-	-	┪	H	┝┈	$\vdash$	$\vdash$	-	$\vdash$	-	Н	H	Н	+-
	$\vdash$	H	H	H	<del> </del>	T	$\vdash$		t	T	H	1	一		H	t	T	T		一	T	T	$\vdash$	$\vdash$	T	T		Г	1	$\vdash$	<del>                                     </del>	-	H	Г	T
			<u> </u>											T		T	T	Γ			Γ														
																	Γ																		



FIELD MEASUREMENTS - 6/81

#### NEW YORK STATE DEPARTMENT OF ENVIRONMENTAL CONSERVATION

JOE	M	Δ1	INI	۰	111	,	Ţ	) <u>A</u> A												SHE	7/	NO.			СН	ECKE	D B	Ÿ	-	DA	ΓE			
SUE	JEC.	Ť						· v	<u> </u>												<del>-/</del> -				CO	MPU LL	TED	BY		DA 7	re / é	94	/31	
$\sqcup$	_	_		Щ	ļ.,	<u> </u>	L	_	_	<b> </b>	L	_		<u> </u>	L			<u> </u>	_	_	_		<u> </u>	Ļ	<u> </u>	L	_	┞	_	-	<u> </u>	<u> </u>	_	L
┥	택	ᄱ	A١	אנ	Δŧ	n	T.	٥	75	RT	Of	ß	be	۰	┡	-	L	_	ω	Εī	R.	F			-	├	-	⊢	-	-	-	-	<u> </u>	┝
H	-	$\dashv$	CR	8	-	-	L	-	-	$\vdash$	71	<u> </u>	H	$\vdash$		$\vdash$	-	├	-		_	CI	н	3	┝	$\vdash$		-	$\vdash$	<del> </del>		$\vdash$		┢
П	$\Box$				+															*	┢													
			Sf	1	当	A	Ų	=	3 1	25												C	•	බ.	63									
Н	_	_	MI	1	E	-0	ς_	•	Ц	20	<u> </u>		_		<u> </u>	_	<u> </u>	_			_	<u> </u>	_		<u> </u>	L	_	_	L	_	_	_	$\Box$	
Н	-	4	•	_	-	<u>_</u>	-			┡	1	$\vdash$	Ļ	_		<u></u>	-	_	_	<u> </u>	Ļ	-	<del> -</del>		Ļ	_	<u> </u>	<u> </u>	_	_	-	-	_	_
Н	-		••	0	VΕ	KŢ	or	PV	၁၆	⊢	-	$\vdash$	Ë	3	30	<b>P</b>	-	H	0	┞┋	LE	ν.	1	93	.8	_		-		┝			H	-
H	┪				-	$\vdash$				$\vdash$		$\vdash$			-	-		-					$\vdash$		一					T	┢╌	-		一
П	$\dashv$				L	Ĺ																	<u> </u>							L	L			
Ц	_	_				<u> </u>	ļ	_	<u> </u>	<u> </u>	-	<u> </u>	$\vdash$		_	_	_	<u> </u>	_	_	<u> </u>	_	L	<u> </u>	<u> </u>	_		ļ		$\vdash$	_	<u> </u>	_	L
${oldsymbol{ech}}$	-	$\dashv$	$\vdash$	_	-	├	-	-	-	<u> </u>	-	-	-			_		$\vdash$	$\vdash$	-	-	-	-	$\vdash$	-	$\vdash$	-	-	-	┢	<u> </u>	-	-	<b> </b>
H	ᅥ	ㅓ			-	<del> </del>	$\vdash$		$\vdash$	$\vdash$	<del>                                     </del>	$\vdash$	$\vdash$		<del> </del>	$\vdash$	<del> </del>	-	$\vdash$	$\vdash$	-	$\vdash$	+		$\vdash$	一	$\vdash$		-	$\vdash$	<u> </u>	-	-	$\vdash$
H	┪	┪				H				_		Т	Г				<u> </u>				-		Т	-	H			Г		T				Г
																						_			_			L	<u> </u>					
Н		4	_		_	-	-	-		_					<u> </u>	_	_	_			<u> </u>	_		$\vdash$	-	<u> </u>		-	┝				_	
Н	-	$\dashv$	$\vdash$			$\vdash$	-	Н	Н		H			Н	-	-	├	_		H	_	<del> </del>	_		-	$\vdash$	-	-	┝	$\vdash$	_	-	_	
	7	┪					┝	Н					Н	_	-	-	$\vdash$	-		_	$\vdash$	-	-	H	┪			┢	一		Н			
														_	_																			
						П	Ц											Ц																
Ц	4	_					_	$\vdash$	_	_	<u> </u>		_		_	L	_	_			_	<u> </u>	<u> </u>	$\sqcup$			L	L	<u> </u>			_		L
$\vdash$	-		$\dashv$	Щ	$\vdash$	-	$\vdash$	$\vdash$	Н	H	Н		Н	Щ	_	<del> </del>	-		_	Н	_	$\vdash$	<del> </del>	$\vdash$	_	$\vdash$	$\vdash$	<u> </u>	<u> </u>	$\vdash$		_	-	L
$\vdash$	ᅱ	ᅥ			$\vdash$	H	H	Н	$\vdash$	$\vdash$	$\vdash$		Н	H	┝	-		$\vdash$		H	$\vdash$	$\vdash$	-	$\vdash$	┝	H	$\vdash$	┢	$\vdash$	$\vdash$				_
$\dashv$	7			П	Н	Н	H	H	H	_	H		H	Н						$\vdash$		$\vdash$	一	Н						Г				
	$\Box$	$\Box$			$\Box$				Ц	$\Box$											L	<u> </u>		$\Box$		$\Box$	Щ							
$\sqcup$	_	_		Щ	Ь,	H	<u> </u>	L	Щ	$\vdash$	Щ		Н	Щ	_	_			-	ļ.	-	<u> </u>	<del> </del>	$\vdash$	_		$\vdash$	<u> </u>		<u> </u>				
Н	ᆉ	-	$\dashv$	$\vdash$	<u> </u>	-	$\vdash$	$\vdash$	Н	-	-		Н			-	$\vdash$		-	-	-	<del> </del>	├	$\vdash$	-		$\vdash$	_	$\vdash$	H	_	Н	Н	
$\vdash$	+	$\dashv$		H	Н	Н	H	Н	H	$\vdash$	H		Н	Н		H				Н	$\vdash$		-	Н	$\vdash$	$\vdash$	Н	_	H	-	Н	Н		_
1	1	7			Н		Н	Н		Н					Т	$\vdash$																		_
$\Box$	$\Box$																			Ц			ļ	Щ						Щ				
_	4	_	_	Щ		Щ	$\vdash$	Н		Щ.			$\vdash$	_		_	H			$\vdash$	$\vdash$	$\vdash$	<u> </u>	Н	$\vdash$		Н			Н		Н		_
$\dashv$	-	-	$\dashv$		-	$\vdash$	Н	Н	Н	$\vdash$	Н		Н		_	-	$\vdash$	Н	$\vdash$	-	$\vdash$	$\vdash$	-	Н	$\vdash$	Н	Н	Н	-	Н	H	$\vdash$	Н	
$\vdash$	+	┪	$\neg$		-	-		$\vdash$		-	-	Н		-	$\vdash$	-		Н		H	<del> </del>	-		H	<u> </u>	Н	$\vdash$	-	-	Н			Н	_



MEU YUKK STATE DEFT OF EWVINGUMENTAL CONSERVATION FLOOD PROTECTION BUREAU .7270 SUSSAGE S CLINION COUNTY CLINION COUNTY SNYPER UN UI! SUBBASI PMF ROUTED OUTFLOW LAGGED HYDROGRAPH -- LAKE FLOWER DAM -- PWASE 1-DALE - 5956 EVO CHANNEL ROUTING -- SARANAL RIVER -- LAKE FLOWER TO 288552 0.00462 3.0 NAIN MILL DAM OCC 2564-254 CHAMPLAIN -- SARAHAG RIVER IMPERIAL PAPER CO. 3 25.0 310A 1.24 1.23 0.22 LVRBSN 1.045 SARRIV 0.21 LKFLUR FLOOD HYDROGRAPH PACKAGL (HLC-1)
DAN SAFETY VLRSION JULY 1978.
LAST MODIFICATION 26 FEB 79 MODIFIED FOR MONEY-JELL APR 79 A1 NY-262 8737. 6-055 0.20 

į

C			C	C	;	σ	C	5	С	•	j	•	•	)	•	Ç	}	•	8	)	0	0		0	0	Č	<b>)</b>	٦,	gar.
		!					i :	i		! .	i i		l	İ		1 i	1		! !	·			1		i .		· i		:
		•		t	1		l			1	1		i .	•	٠	1	1		i		٠.		1		•	•	i		! !
		•		! {	!			1		: 			! !	1		!	-		! . ;	† :		<u> </u>	1		1	i			
		•		!	!		;	•	•	•	i		i	1		•	!						ı		:	į	İ		•
		1			i		  - 			! !	1		!			† f	!		!	i		!	1		1	!	1		!
		,			1		i t	!		! i .	i		i	1		1	1		:	;		ŧ	1		!	1	1	. •	
	•	:		<b>!</b> !			!		301	• •	1	190.3		420		! !	į		:	į		!			:		i		
		:					!		FLASMBOARDS		.	13		7		•	!		i	1		<u>.</u>			1 -				
	-	:		;	}		:	;	E FLA	•	1	190	195.6	5760	22382	:   	•			•		:	1		1	!			1
			1.0	i ;	i I		<b>!</b>	•	05	i ;	7	169	195.1	3741	19998	! 	<b>₹</b> ₹		·.	,			!		i	į	1	•	!
		i	_	,	<b>,</b>		: •	•			١.			;	•	•	• :		•	•			, .		1	t	1		!
			7.8				3	-	DSED		-186	188.5	195	2846	19666			•							•				
~	,	95	•		. •	••	INFLOU		FLOOD GATE CLOSED			188	134	2036	16441	2182	203									_	:		
•	•						DAM		79 000	-	٠	s.																	
MEST	. 9	 <b>49</b>					AT		•			187.5	193.8	1322	15820	1413	193.8								•			•	
RUNOFF LOVER SUBBASIN		74.5		•			GRAPHS		- DAM	-		187	193	720	13419	970	188.5		330	-									
LOVE	429	ŝ			1.3		COMBINED HYDROGRA		ROUTED OUTFLOW -			ĸ,	~	•		1			ญ						•				
066	7	57			ä		BINED		TED 04			186.5	192	254	10615	141	186		1.5										•
NO.		9		9.56	-0.5	DAR	00	DAM	300			186	191	•	8051	310	174		2.63			,							
	-			19	828	~					-	174	•	•	11		164	186	•	:									
=	-	•	_	_	•	<b>.</b>	<b>.</b>		Z.		7.1	Y 1	Y4 190.8	7.5	YS 7571	\$	\$£ 1	\$\$ 1	\$D 193.8			_		_	_				
•	-		_	•	-	-	•	•	•		•					•	•	•	•	=				•					
																			٠	•	•			·					
	~	•	•	•			•		•	_	۸.	•	•	•			<b></b>			_	<b>A</b> 1	•	•••	•		•			·
•	ñ	33	*	35	36	37	38	<b>8</b>		•	45	4.3	ř	¥	7		7	*	2	5	52	88	\$	ъ́	ā		٠		
				,	٠.	·				. •	1.=		•	•				. 🕳 .		•		,	•.		,	1.44	ı		٠
																													-

i

~

-

1

ŧ

1

í

•

٠.. -

FALVIEW OF SLUCENCE OF STREAM HITTONICALCULATIONS
AUNDER HYDROGRAPH AT LYRELY
ROUTE HYDROGRAPH AT LYBROSH
COMBINE 2 HYDROGRAPH AT LYBRSH
COMBINE 2 HYDROGRAPHS AT DAM
ROUTE HYDROGRAPH TO DAM
ROUTE HYDROGRAPH TO DAM

DAN SAFETY VERSION JULY 1973 LAST MODIFICATION 26 FEB 79 MODIFICO FOR MONEYMELL APR 79 FLOOD HYDROGRAPH PACKAGE (INC-1) \*

NEW YORK STATE DEPT OF ENVIRONMENTAL CONSERVATION FLOOD PROTECTION BUREAU

1 .	· !				1 1	!		
:		i i		, , ,		354.	9513. 8811. 8065.	25.25 25 25.25 25 25 25 25 25 25 25 25 25 25 25 25 2
i	· · · · · · · · · · · · · · · · · · ·	•		14070	j 1 :	!	;	1 1
BASIN	SSTAR STAR			AGE	LOCAL	384	9563	2000 2000 2000 2000 2000 2000 2000 200
LAIN BA UNTY UI/ SUB	TAGE :			9	ISANE 1.	354.	9603. 8960. 8217.	5551. 5551. 5551. 5732. 2853.
LAKE CHAMPLAIN CLINTON COUNTY SNYDER UN VI/ S	• •				NONSI	•,	· ·	
CL13 SNY	IPLT	RHED 0.50		1 MAG 1 PR 1		354.	9629. 9034. 8293.	24 25 25 25 25 25 25 25 25 25 25 25 25 25
RIVER	METRC METRC TRACE	E PERFORMED R710= 1 0.25 0		COMPUTATION LAKE FLOVER PE JPLT	BATIO	######################################	9538. 9108. 8367.	2006. 2006. 2006. 2006.
SARANAC	FICAȚIO INIK LROPI	. <b>₽ → ₹</b>			PH DATA TRSPC	DROGRAP 3		
1 MILL DAM 2364-234 CHAMPLAIN SARANAC RIAL PAPER CO.	JOB SPECIFICATION INTE B NUT LROPI	ANALYSES TO I WRTIOG A 0.23 0.	***************************************	_	HYDROGRAPH DATA TRSDA TRSPC 179.00 0.	INPUT HYDROGRAPH 354. 35	9626. 9182. 8442.	6835. 6901. 4091. 4079. 3108.
CHAMPL CHAMPL ER COS	10AY 10PER 5	MULTI-PLAN NPLAN= -21 0.22	•	SUB-AREA RUNI LAGGED HYDROGRAPH ICONP IECON	SNAP 0.	354. 354.	9586. 9254. 8516.	5996. 5996. 5974. 5188. 5485.
HAIN MILL DAM Dec 2364-234 Champ Imperial Paper CO.	7	MULT:	•	LAGGE	TAREA 179.66			•
MAIN MILL DEC 2364-3 Imperial F	# •			OUTFLOU 1stag Lkflur		484. 854.	9407	60915 60915 5157 4279 2279
-562	. # **	7105=		ROUTED	9H51	354.	716. 392. 663.	100. 100. 126. 1270. 1561.
**	120	74		78	IHYDG -1	N FO	E C 2	
28/81						354.	6929. 9455. 8737.	4461. 2556. 2556. 2556. 2556.
DATE 87/28/81						. •	• •	
		:	•		•	· ·•	•	

HYDROGRAPH AT STALKFLUR FOR PLAN 1. RTIO 1

101AL VOLUME 624699. 17689. 16.23 412.30

5.70 144.84 54411. 67115.

24-110UR 9914. 271. 10-99 15-95 15-98 15-98

9633. 273. 273. 0.50 12.72 4777.

CFS CAS TNCHES

0

0

18 8 8 8 m

0

AC-FT THOUS CU M

72-HOUR 9144. 259.

12 55 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5		100000 100000 100000 100000 100000 100000 100000 100000 1000000			!
1911 1611 1611 1611 1611 1611 1611 1611					
11 14 14 14 14 14 14 14 14 14 14 14 14 1	AL VOLUME 124990- 35380- 3.25 82.46 30977- 38289	11000000000000000000000000000000000000	1	2011 10011 10011 10011 10011 10011 10011 10011 10011	AL VOLUME
11 12 12 13 14 14 14 14 14 14 14 14 14 14 14 14 14	101 101 101 101 101 101 101 101 101 101	1. #110 2 74. 74. 10022. 10097. 115742. 11997. 11997. 621. 6621.	HOUR TOTA 920. 54. 1.28 426. 094.	10 2 10 10 10 10 10 10 10 10 10 10 10 10 10 1	101 AUG
		P			H-21 NOUR
11000000000000000000000000000000000000	200 200 200 200 200 200 200 200 200 200	7 X X X X X X X X X X X X X X X X X X X	200R 253. 57. 57.	11 X X X X X X X X X X X X X X X X X X	5-HOUR 24-HOU
	PEAK BSSsssssssssssssssssssssssssssssssssss	06 RAPH A1 20 14 11 19 14 11 19 19 19 19 19 19 19 19 19 19 19 19	50 4 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6	APN APN APN APN APN APN APN APN APN APN	_
	CFS 199 CMS 199 INCHES AR AC-FT AS	11 14 14 14 14 14 14 14 14 14 14 14 14 1	CFS 200 CAS 200 INCHES AN AN ACT I	12000 12000	PCA
1235. 1235. 1235. 1237. 1237. 1019.	INC AC. THOUS CI	74. 18.30. 1972. 1819. 1891. 1891. 1865.	INC.	78. 1916. 1966. 1966. 1766. 1161. 1151. 961.	
11291 11291 11291 11291 11295 1992 1992		110000 110000 110000 110000 11000 11000 11000 11000 11000		78. 1824. 2888. 11922. 11597. 11582. 1174. 981.	

The state of the s

	<u> </u>	i	,		;:  :							1	•	ļ.	·				- -			•	•			i.		,			•		;	-		ı İ	
	<b>!</b>	1 -	İ		<b>(</b>		ł ,		1			i				. ,			•			•	i		•	į	•	1			; •		;		ŀ	1	
	. 1						1		1			!		i		1			!		1 .	•	<u>.</u>	••		1				••	1	:	:				
		i	•		! !		,					:		,		,						•	• '			1		. '		-	;		•		!	!	•
•	i	ł	İ		!	Ì	į		1			•		İ	•	;			į		1		į			!		٠,		•	1	,	ţ		İ	İ	
686.			1	177.	1	4406.	+033.	3633.	2715.	2276.	1775.	-1367.	932.						1		18.4		2	6811.	. 6965	7278	5420	4552.	3556.	2733.			1		1		
912. 702. 515.	!			177.		43.	•								•	•			!			194				•	• •			•			1				
878		•	i			•	101	3:	2762	2321	1824	1		i		!			•		,	3	9563	6889	8141	7353	35.5	464	3646	2 ;	•		•		į	ĺ	
45.6 45.6 50.5 50.5 50.5	. VOLUME 156174. 4922. 103.07	47762.	: ;	177.	. 2	4480.	109	3718	36010	2366.	1876.	1442.	8	401		9 6	_	77442.	12223		484		9683.	8960.	8217.	7435.	5617	4732	3751.	2663.	7193	YOL	624698		412.30	188	
552	1014		110 7	177.	1615.	4517.	4147.	3757.	2327.	2410	1928.	1479.	1184.	TOTAL							2 0 E		)629°	9034.	8293.	7514.	7011.	4820	3856.	2958.	•	TOTAL			:	· :	
492. 758. 571.	72-HOUR 2286. 65. 1-43	156	L'AN 1. R	177.						54.	83.		142.	72-HOUR	4572	2.85	72-42	27206.	32356.		PLAN 10 K		38.					•	•	3050		2	<b>T</b> 5	259.		1111	
-	2393. 68. 0.50	4747. 5856.	WR FOR	•	. •	•	•				•	-	-	ê.	4787		25.27	9495	-11/11		F0 F			•								3	9574	271.	50.55	18989.	
1020-	N	•	- L	177	4815	4591	4221	2323	2448	2496			. 1179	S SOUR	•		36		•		STALKFLUI	2	Ş		8442	7669	0000 0000	991	179	3108	) ) )	2	<b>.</b>	•			
796.	6-HOUR 2408* 68* 68* 3-18		2 11	177.	795.	627.	258.	5,79	900	537.	. 160	595.	217.	I	184			2388.	294	:	14 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4		586.	254.	516.	750.	966	97.	188.	5185.	• • • • •	BOOK-9	46.5	2	12.72	417	
9 ganti	PEAK 2410. 68.		DROGE											PEAK	1819.	• • • • • • • • • • • • • • • • • • • •					MYDROGRAP											PEAK	9636.	273.			
1070.		- X	AH	177.	.70.	4662.	4295	3913	4000	2579.	2140.	1636.	1254.				<b>*</b>	<u>.</u>	E				9487	9324.	6589.	7830	6 B 9 1	5157	4279.	3272.					2 2	F 7	
6.66	CFS CAS IRCHES	AC-L THOUS CU	!	177.	4358	1696.	4532.	5935		2622.	2105.	1681.	1292.		ជ ប៉	1808I	_	AC-F1	23 S00H1		16.	48.6	8716.	9392.	8663.	7309.	6186	5243.	4370.	3361.	**************************************		ថ (	が正じると	[ ] [ ]	AC-FT	
1115. 1661. 1651.				177	3465	4728.	4369	6444	3353	.668.	1231.	1727.	329.								16.0	180	929	1455.	1737.	7987.	.280.	356.	1461.	3434.	• • • •		•				

7.0

C 0

-26034.16 219759-64 228.95 250.00 58420.35 219739.04 199581.67 22789.93 5665.29 226.84 199581-67 --19688-62 \$4252-85 186381.68 100301-68 224.74. IAUTO 131AGE ISPRAT 26344.96. 16190.22-161903.54 - 222.63 28344.98 243.68 1669. 1856. 1784. 1550. 210.60 STORA SARANAC RIVER -- LAKE FLOWER TO DAM Jecon Itape Jpli Jpri Ina 20395,25 20395.25 165.00 210.00 215.00 13433.70 220.53 1566. 1483. 1239. 1033. 32. **-**IPAP 655. STATION' SARRIV. PLAN 1. RTIO 1 TOPT 13558.96 10436.10 43198.99 218.42 13558.96 652. 1733. 1733. 1862. 1828. 1838. HYUROGRAP! ROUTING ROUTING DATA . \*\*\*\*\*\*\*\*\* ISAME OUTFL. OU ELMAX RLWTH SEL 250.0 288552. 0.00462 CROSS SECTION COORDINATES--STA, ELEV-STC SD-80 250.00 212.00 222.00 300.00 232.00 250.00 250.00 7912.15 7912.15 216.32 237.37 7497.21 59640.20 IRES 203. 203. 1900. 1765. 1613. 1275. CNAMMEL BOUTING -1STAG ICONP SARRIV 1 MS TOL 3570.65 4617.04 36144.32 214.21 3570.65 97253.53 CLOSS 11294 11294 11294 11294 11294 11294 11294 1705.59 32711.35 746.94 83369.27 746.94 83369.27 212-11 233-16 91.055 0M(3) 82. 89. 1912. 1792. 1644. 1487. 1313. 1354. MORMAL DEPTH CHANNEL ROUTING QN(2) 29341.38 70419.57 210.00 78419.57 1908. 1807. 1659. 1593. \$£5 5.15 5.17 08(1) 0.0558 FLOU STAGE OUTFL 39 STORAGE

€, **3** , **3** . . . .

917. 917. 917. 917. 917. 917. 917. 917.
1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1,
911. 577. 577. 577. 577. 577. 577. 577. 5
211. 5.17. 5
911
211. 5.72. 1.71. 1
211. 5.72. 5.41. 5.42. 5.41. 5.42. 5.41. 5.42. 5
210.0 2.12.0 2.1
·

4616, 4616,
115. 115. 115. 115. 115. 115. 115. 115.
110. 446. 447. 441. 447. 447. 447. 447. 447. 447
418. 448. 441. 441. 441. 441. 441. 441.
110.  110.
212.0 218.0 21
210.0 210.0
2010 2010
**************************************
·A

3 3 3

----

10515	212-1	212.1	212.1	212.	77.	2.0	212.0	212.0	211.9	211.9	
•			•	-HOUR 2	Ŧ	72-HOUR	TOTAL	_			
	55		2391. 2 68.	2 Z	2368. 67.	2254.		156430.	:		•
	INCHE		•	~ ~	90			3.91	:	•	į
	AC-FT THOUS CU M			1185. 1461.	5793	13414.	•	37297.	•		
								•	1	-	-
			MAXIMUM	JN STORAG	# <b>!!</b>	688.					
MAXIMUM STAGE IS	213.3				•		•	<b>!</b>		•	
			STATIO	ON SARI	V. PLAN	1. RTIO	_	•	!		
				30	UTFLOW .					•	
	•	•	01	21,		35	3	69	5	103.	
	131.	141	158.	157	~ 5	6. Z.	166.	169.	172.	175.	
•1624	4770	Š	4716	4684		20.	615	- 1579.	2	4505	
4468.	4431.	4394.	357	320		83.	246	4209.	4171.	4134.	
4096.	4058.	4020.	981	941		92.	862	3823.	2	3744.	٠
*010	3663.	3622.	583	558		33.	66.5	3459.	2	.3372.	-
5557	2761.	9763	188	141			7 T T	25.19	2492	2450	
2410	2366	2322	2277	232		. 98	) —	2089	3	1984	
1931.	1879.	1828.	1779.	731	19.	85.	2	1598.	2	1519.	
1481.	1443.	1405.	1368.	330	•	93.	255	1218.	2	1143.	,
					108		• •				!
	•	<b>.</b>	·6		•	17.	25.	33.	45.	. 20	
57.	63.	<b>.</b> 68 .	72.	75	•	78.	•	2	85	2	!
- 1.V	֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֡֓֓֓֡֓֓֓֓֡֓֓֡֓֡	1079	101	101		567.	640	1057		1047	
1042	1038	1033.	1028	1023		18.	1013.	1008	1003.	996	İ
. 993.	988	983.	978.	973		67.	962	957	25	946.	
941.	936.	930.	925.	921		~ (	6	901.	2	• • • • •	
975	366	856.	647.	600		N	1,	.60%	2 6	796.	; ;
197	67.10 68.13	707	133.			7 4	637	627	2 2	• 90 Y	
671.		27.5		5 5 5 5 5 5		•		529	521	513	
506.	498	491.	483	476.		6.B.	5.5	455	446.	438.	
					•	•					
•	_ 4		10	. ב ב				: 4		218.3	! !
: :	: :		: :	: :	•		: :		, 9	210.5	
:		-	12.	13.		5.1		÷	•	-214.8	:
•	;	•	:	:		1.1		÷.	•	214.7	
:	:	•	:	:	•	9.		÷.	•	214.5	
٥.	•	•	÷ :	*	•	•	•	÷.	•	214.5	
٨.	:	•	-	14.	~	~	ė,	•	•	214.1	•
	214.0	214.0	213.9	ř.	21	6.0	213.8	213.8	213.7	213.7	
			2 5	2 2	. 0			213.1	, ,	213.0	!
١,	:							٠.			
١		n	,		=	Z .	ì		м	212-1	

3: 3-13

405.98 151760. 187193. 144.15 54151. 66794. 19048 19062 23589 12.70 4772. 5886. AC-FT THOUS CU M

1678. MAXINUM STORAGE =

> 217.0 MAXIFUP STAGE 15

•			•					
ł	•	! :	ł		•	!	i	1438. 357. 89.
4			1	į - į	i i	ŀ	. 1	5 2 7
********		IAUTO	•		٥.		• !	
•		<b>.</b>	مذ	1	ALSHX RTIMP	ŧ		VOL= 1.0 6651. 1653. 411. 102.
•		}	LOCAL		= -		ì	L= 1- 6651- 1653- 411- 102-
•		ISTAGE	2	i i	!	1	· •	. 10 A
		IST			S.	:	¥	e e
			I SAME	: <b>8</b>	4		, &	630. 630. 900.
•		INAME	~	` <b>*</b> • 1		•	1.30 7.19 INTERVALS	LAGE: 19.02 HOURS, CP= 0.56 .7849. 8177. 7630. 2:10. 2183. 1900. £24. 542. 472. 155. 135. 117.
•		2		;	CNSTL 0.10		9.0	<b>.</b>
		:	ISNOU	R 7 2	20		RTIOR= 1.30 AND R= 7.19	· ·
:		JPRT	18	<b>"</b> .			<u> </u>	HOUR 1177. 1183. 542. 135.
:		7			STATL 1.00		90	HOUR. 817. 2183. 542. 135.
	,		RA T 10	8 4 8 • 0 0	1 2		474 -0.20 RTIOR= 7C= 7.10 AND R=	05
	2	JPLT	A 0	R48 92.00		A NTA=	10	13
	171	ج ک		• • • · · · · · · · · · · · · · · · · ·	RT 10K	HYDROGRAPH DATA CP=0.56 N		7849. 7849. 2110. 624.
_	P		HYDROGRAPH DATA TRSDA TRSPC 608.00 0.		E .	· 3	1414 -0-20 TC= 7	2 × × × ×
:	Ô	P. 0	9 K 9	DATA: R24 85.00	<b>4</b>	ROGRAPH CP=0.56	_	• .
• • • • • • • • •	4.	ITAPE	P.		LOSS DATA Strks 0.	S 0 0 0	RECESSION C ORCSV= AND TP ARE	0RD INATES. 6:805. 1 2884. 717. 178.
•	Š	•	2 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	PREC1P R12	SS STR 0.	5 2	CESS FOR GRESN=	6305- 2884- 717- 178-
:	2	N N O	YDROGR TRSDA 608.00	PREC) R12	7	Ī	200	26.5
	EA	BASIN IECON	7 9		· Z	UNIT 9.00		
	SUB-AREA RUNOFF COMPUTATION	LOYER SUBBASIN ICOMP IECON	SNAP 0.	• •	ERAIN 0.	11NU 19.00	STRTG= 858.00 GIVEN SNYDER CP	IT HYDROGRAPH 42 END-OF-PERIOD 1658. 3324. 5174. 4380. 3811. 3315. 1088. 947. 824. 270. 235. 205.
	AUS	ے گے 6	SN.	R6 59.00		1 b =	858.00 YOER C	-PER1
•	٠,	OVER 1COMP		NO.	1.00 1.00	=	8 ×	I WW
********		3-	E &	v o	RTTOL 1.00		STRTG= GIVEN S	0-6
:		102	TAREA	PHS 16.00			TRT	ž
:		RUNDFF - ISTAG Lurbsn	- 3	7 8	æ		2 G	42 Ei 3324 • 3811 • 947 •
•		3-3	<b>9</b> -	ш <b>е</b>	DLTKR 0.		5	* m w
		Œ	10HG	SPFE 0. 1s	_		ī.	¥
				W 0 X	æ		N T S	10x 00 15x . 180 . 170 . 67 .
			<b>9</b> ~	SPFE 0. 16 Program is 0.903	STRKR 0.		11.	1658. 4580. 1088. 270. 67.
:		•	IHYDG 1	ä	•,		F10	<b>+</b>
			-	Ή	- 0		OCF	25
•••••				=	LROPT		ŭ	
:				5	-		A A	5055 1251 511
				آر 10			7	
				5			7	-
				X O	•		Ž.	
				ب			Š	
				TRSPC COMPUTED BY THE			APPROXIMATE CLARK COEFFICIENTS FROM	
			• .	•			. ₹	

COMP 0 HR.MN 15.00 18.00 21.00 2.00 2.00 2.00 2.00 2.00 3.00 END-OF-PERIOD FLOU 836. 1508 814. 1508 814. 1508 773. 1509 753. 1509 714. 1509 677. 1509 677. 1509 677. 1509 687. 1509 5866. 1509 2.32 6.00 112.00 113.00 21.00 0.00 3.00 6.00 9.00 12.00 15.00 40.01 11.01 10.01 10.01

1

	,		•	•,			,			, .					•	:		•	:	•	•	•	:	•		•		•	• .	: !	<b>-</b> ,	:	•	• i		•		<b>q</b>	•	•	<b>-</b> ,	-	-			
																1			1								1					1		,			•	٠,	•			· •		· · · · · · · · · · · · · · · · · · ·		•
•	*4997	*870°	4744.	623	- 1004	2 6	4161.	53	948	3846	3746.	3649.	. 3555	3463.	5373.	3286	3200.	3118.	3037	2958	2807	27.54	2664	2595	2527.	2462.	2398.	2336.	2217	2159.	2103.	2049.	966	1894	5	1797.	1750.	1/05.	1618.	1576.	1535.	352336	8293.89			!
•	•	•	•		•	• •		•			•		!	•	ċ		•	•	; •	•	• •	• •			•	•		•	•		•	1		•		•	•				:	3.41	87.10	!		; ! !
• :a	•	•			• •		• •	:			•	•	0	•	•		•	•	<b>.</b>	•	• •		9			•	•	• •	• e			•	<b>.</b>	• •		•	•	•	• • •		•	9.89	( ,251.)	!		
2	9	0	•	9 (	D 6	<b>&gt;</b> c		•	•	•	0	•	0	0	•	• 0 ::	•	0		<b>.</b>			· a		0	•	0	0	•	0	0	•	<b>•</b> •	• •	•	•	0	5 6		•	•	13.38	338	0LUME 1155.	260.	•
1.	•	~	_ '	~ 1	2	0 0		•		-			•	30	•	•	6	6	<b>5</b> (	<b>a</b> 0	9 6			101	~	10.2	•	-	105	11	108	109	110	111	=======================================		=	Ξ:	7 .	119	120	MAS		TOTAL VOLI	27	
	9.0	12.0	0 15	0 18.0	2			9.6	12.0	15.0	18.0	5 2	•	•	9	9.6	12.0	15.0	18.0	7 9	4 6	,	6	12	15.0	18.0		• •		9.0	12.0	15.0	~ .	10.17	נייו נ	6.0	0.6	12.0	18,00	21.0		•		2-HOUR. 36799.	042	
		1.1	-			7 -			-	• -	-	•	-	1.1	1.1	1-1	1.1		~ .	-				1.1	-	1-1						1:1					~				1:1			, 72 E		
•	/Hich.	3972	59640	71457	7.184		67215.	53414	522	0522	3301.	0757	6803.	3362.	036.7.	~	5491.	5048.	9 (	4279.	1549.		25.6	523	12199.	883.	.576.	1276.	0.584 0.549	0422	0152.	.889	9653.	9384	904	8674.	1449.		3 2		7			5°		
.80	30 2	30								. 4	. •0	כייו נ	~	~	· Cu	-	7	-	- '		~ -	-						~ •	-	<b>-</b>	~						-							6-HOUR 75569.	2346	
n 14.	. 16	.16	•	•	•	•	•						•	•	•	•	•	•	•	•	•	•			•	•	•	•	•	• •		•	•	• •		•		•	•	•	• •			PEAK 77184.		
٠,٠	.46	94.	•	•		•	•							•					•		•	• •				•	•	•	•				•	•				•	•	•				CFS	'n	
																												• 1	n 4	۰ م	•	•	۰.	۰ د	. m	•	<b>س</b>	<b>.</b>	~ a							
=	21.00	•	2.00	00.9	9.0	) (	00.01	9		00.5	00.4	. 00*6	2.0	240	8.0	21.00	•	3.00	00-9	6	15.00				3.00	6.00		5.0		21.00		3.00	9.00	30.00		:	21.00		7.00		12.00					
=	•	•	•	•	•	÷ (	•	•		•		•	. •	9		•	•	•	•	9	•	9 9	? =	? ?	•	•	•	•	9 9	•		•	•	2	20	101	20	80	•	; =	1.08					

**************************************		384. 38235. 10184. 6262. 4817. 3705. 2850. 2850. 1686. 1297.		667. 76469. 20367. 12523. 9633. 7410. 5700. 4385. 1996. 1596.
8666. 512. 394.		28592 11681 11681 14945 13945 13945 1345 1345 1824 1824		679. 771184. 231584. 12856. 9889. 7607. 5862. 4561. 1976.
2264 5264 5264	AL VOLUME 337789. 9565. 3.66 93.02 83749.	35 71 48 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8	AL VOLUME 675578- 19130- 19130- 186- 167499- 206606-	696. 1145. 10152. 10152. 10152. 7810. 8621. 2755. 2105. 1618. 1851155. 1865.
215 702 540 156	261. 261. 261. 2.39 60.88	11. RTIO 7 25820- 15579- 65714- 65714- 22715- 1825- 11484- 11484- 11660-	000R T01 221. 279 61. 67.	1. KTIO B 25040. 100520. 100520. 100520. 20017. 20017. 20017. 20017. 20017. 20017. 20017. 20017. 20017.
557	-HOUR 72-455-455-455-455-455-455-455-455-455-45	707 PLAN 21976- 21976- 17651- 5955- 5955- 5456- 11676- 11687- 11687- 11687- 11687-	2159. 12 2159. 12 2159. 13 2010. 13 860. 13 860. 13	A FOR PLAN 1000010 10000010 100000000
	6-NOUA 24 16692. 1 505. 0.41 19.64 11555. 5	AT STALLMRUSS 3 16 - 1595 5 - 2026 1 - 2026 1 - 2506 - 2506 - 1925 6 - 192	- MOUR 2 7794. 10 70 40 60 80 80 80 80 80 80 80 80 80 80 80 80 80	1
7788	2000 2000 2000 2000 2000 2000	200 FO STAND	<b>*</b> • •	00068797 114657 114657 116657
7	CFS CNS INCHES AR AC-FT		CFS CMS CMS CMFS CC-F1	2
1534. 1557. D68. 1040. 821. 860. 632. 615.	THO	418. 407. 514. 1192. 4958. 30621. 6108. 5942. 6108. 5942. 5609. 3516. 2776. 2784. 2776. 2784. 1643. 1600. 1264. 1231.	THOUS	
		418. 34958. 84958. 61908. 4692. 3699. 2776. 1264.		836. 1028. 69914. 17760. 12199. 9384. 9284. 9284. 1944.

				,	COMBINE H	HY DROGRAPHS	SHA								
				•											١
•		-	COMBINED H		FORGGRAPHS AT DAM ICOMP IECON 2	ITAPE J	104 JPLT	4	INAME 1	BSTAGE - 0	1AUTO	•	. 1	1	·
			SUM OF	2 HYDROGRAPHS	TA SHE	Ä	PLAN 1	1 0118		,	1		į		•
	167.	163.	166.	159.	159.		£1.	163.	167.		•	175.			
	255.	529.	1230.	2903				11994.	14355.	25586		15564.			
	*****	12557	7000	4564	8454		7775. 8659.	19610		ł	16.	4326	İ		<b>!</b>
	2400 4247	1690	- 100	400	2000		1730	3808	3734			3600.			
	3556	3472	3409.	2548			3228.	5170.	3112.	3056.	•	3061.	i	1	
	2947.	2893.	2041.	2788.	~		2686.	2636.	2587.		•	2489.	•		
• .	2441.	2394.	2348.	2302.			2212.	2167.	2124		-	2039.	,		
•	1997.	1956.	1916.	1076.	<b>~</b> ′		1000.	1763.	1727.	<b>,</b>		1656.	Ì	!	1
	1621.	1587	1552.	228			.151	1417.	η.	~ .	***	1510			
	1288.	1251.	1228.	1212.	- C411 - 896		176.	920.	896	•		849	į		ı
•	3						2		1		•				
•			Ē	AK 6	~	4-HOUR	72-HOUR	R TOTAL	YOLUME.		-	_	-		
		_		.90		•	8316.	•	ž.			!	į	•	i !
	•	-	•		4.30.	36701	235	• •	11059.						٠
		4 3 5 3 5 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	16.00 10.00		9.25	16.79			26.59						
				•		26687	48484	,	. •		1	1 ·	i	<b>!</b> -	
		THOUS CU		- <b>-</b>	9286	31684.	61037		119436						•
•			: :			-		;				1	i		,
				•											
			Silve Of	2 MYDROGRAPHS	RAPHS AT	DAM	PLAN 1	RT10 2.	:	1		:	1	1	!
•	176.	171.	-	167.	167			172.	175.		.6	184.	ı		
	246	556.	1291.	3048	5918			12594.	15073.	16281		16132.			
	14761.	12954.	11348.	9988.	•		8137.	7896.	7411.	ı	54.	6262.	!	1	1
	5734.	5261.	5165.	5073.	4 482.		4892.	4808.	4715.			4543		•	•
	4459.	4377	4297.	4219.	•		4067	3993	3921.		•	3780.			-
	3712.	3645.	4556	3515.		• •	587.	3328.	3208.	. 520%		1010	•	<u>i</u>	۱ <b>.</b>
	26.4	00000	2763	2417	6726		120	2276	2230		2	2141		-	
	- 1962	2050	2012	1970			889.	1651	1813.	177	776	1739.	. !		- 1
ı		1666.	1630.	1594	1558		523.	1488.	1452.	•	.5	1378.			
	1342.	1307	1274.	247	1225.		209.	1192.	2	-	13.	1132.	-		
,	1109.		1862.	1038.	1013		989.	. 964.	940			.168	•	1	•
			Ĺ	EAK	-HOUR 24	4-HOUR	72-HOUR	R TOTAL	VOLUME			:		-	
		•	162	-		-	•		7	•	-	1	.:	i	
		CHS	•	11.	451.	385.	248.	•	11612.				٠.	•	
						20.0	9.7		*1.0				•	•	
				•		11.17	40010	t	101672		•	:	•	·	ı
		UN SUONI	# DO :	- <b>-</b>		33270.	64154		125411.						
.:						•		•	1		1	!	t į		ł
			SUR OF	2 HYDROGRAPHS		940	FLAN 1	RTIO 3	.,	į		,	;	ļ !	,
	1981	100.	176.	175	175		177.	180.	184.	186		192.			

i

**1** 

;

******					
, - i.e			e grand de la company	ng grand <b>e</b> n en	tent of materials
1	· · · · · · · · · · · · · · · · · · ·	· · · · · · · · · · · · · · · · · · ·			
•	, i	( ) ( )	i i t	a fill in the	1 1 1
	!		:		
•	' !		' ! !		
	•				· · · · · · · · · · · · · · · · · · ·
•	1 1	1 1 1	! } }		
	• • •				• • •
	219 9205 7463	25 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5		437 38410 114969 114969 7449 6223 6223 4140 4140 1140 1140 1140	874 29967
•	1 7			MAR	Fig
•	* * *				
•	213 9382 8158	25509 25509 25101 25101 10268		100 100 100 100 100 100 100 100 100 100	885. 17526
•	7	1 1	F 1 - 1	naa j	Fin
			# 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6		
5571 5071 5071 5071 5071	209 7944 8889	2565 2565 2565 2565 2565 2565 2565 2565	240.000	417. 1828. 1828. 11176. 11176. 1728. 1728. 1728. 1728. 1728. 1728. 1728.	279510. 27757. 27757. 17.49 19.5. 19
116			781, 22		~~~ .~ .~
	•		OTAL	0	10 P
	8710 204. 993.	2202. 2205. 2205. 2205. 1360.	=	84498499999999999999999999999999999999	T T T T T T T T T T T T T T T T T T T
	76	K O F P P N N N	300R 399. 117.		2020-0- 4
4 B B	*		1207973	*	72 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 -
	20 PL	4 - 2 - 2 - 2 - 2 - 2 - 2 - 2 - 2 - 2 -	7 9	AM PLAN 401. 22148. 215948. 31594. 9632. 9632. 4693. 3626. 2743.	72 11 22 68 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6
	4025		5 9 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5	0 4 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	~
			7240000		
. 88	- 6 4 0 6 4 5 5	2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	*		- 128
	1S A 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		# : : # # : :	11 22 11 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	7766
0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	RAPHS		6-H0US 5373 6-27 7-31 9411	-	10795.0 10795.
• 3	YDROGI 198. 3628.			HYDROGR 241. 221. 221. 221. 221. 9991. 9991. 9991. 9791. 3791. 226.	. 379 . 104 118 118 118 118 118 118 118 118 118 11
•	HYDROGRA 198. 3628.		× • •	HVDROG 347. 7251. 24631. 12995. 9399. 69318. 69318. 5795.	MYDRO 1 1 4 5 1 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5
Ž	~		PEAK 19382. 549.	~	725
	200. 200. 537.	2000 2000 2000 2000 2000 2000 2000 200	<b>=</b>		
10 <b>5-6</b>	20H 20H 153	2000 2000 2000 2000 2000 2000 2000 200	999EFE		2420 6 6 6 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7
AC-FT S CU R			CFS CAS INCHES AC-FT S CU M		SELE SELECTION OF
T 4 S	4 0 0		E VS		7800 18 2846 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6
THOUS	284. 662.	5256. 5261. 5211. 3617. 2993. 2993. 1983. 1293.	1 400%	1323 1323 30865 30865 1023 7170 7170 4896 5966 4896 5966 5966 5966 5966 5966 5966 5966 5	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
	•	•		r: <del></del>	•
	289. 316.	25.5 5.6 5.6 5.6 5.6 5.6 5.6 5.6 5.6 5.6		418. 632. 1146. 1146. 1567. 1313. 1933. 1953.	
	26,	5000 15000 15000 15000 15000 15000 15000 15000 15000	•	632 . 632 .	8 4 6
	-	-		43 tes tes	
•				•	
			•		

:				• •	i		;	95		1	ı	I	i i	i	•	1
			  -  -	!		1	i .	190	6420		1	i	, 	1	•	
1	·	1 1		:	1	1	1	190.00	5760.00 . 22362.00		!	!				
17858. 12328. 18866.	6419. 5035.	i !		1				001	-00		!					15433.
15174. 15174. 10266.	5164. 5164. 5936.				S IAUT	× -		195-1	19998		}					168. 15438. 6578.
		25.0 25.0 25.0 25.0 25.0 25.0 25.0 25.0		:	FLASHBOARD E ISTAGE 1 0	1.51	A ISPRAT	188.50	2846.00-		!	EXPL 0.		! :		164. 14129. 1112. 4505.
18527 12557 12655 10691		101AL VOLUME 196.5552. 55593. 15.02 581.48 466757.		i	N I I		K. STORA -186.	00	90	•		CAREA 0.			ATES	
15741.	5675. 6955. 5436.				208	<b>T</b> .	X TSK	188.6	2036.00	2182.	203.	1005 0.	D DARVID 538.	1. RATIO	APH ORDINATES	116.31
19222. 16030. 15315. 10930.	73.26. 55.75. 4290.	27 787		ROUT 186	ATE CLOSED PE JPLT 0 0 0	1001		187.50	1,522,60	415.		ברבאר 1.	DAM DATA	• PLAN	HYDROGRA	2 150. 2344. 7799.
145.40. 16315. 135.70.	4654. 5713. 4411.	24~HOUR 65.580 1852. 1.08 101.64 129695.	Ť	HYDROGRAPH RO	1000	5	G APSKK	93.00		. 141	Ä .	EXPU	200	N COM		007FLOW 159. 5124. 4582.
		6-HOUR 75913. 2150. 1.16 29.58 37643.	•	MYDRO	DAN -	<b>5</b>	5	167	120.00	976.	189.	C008	TOPEL 193.8	STATIO	END-0F	• • • •
26231 26231 26231 26231		PEAK 77528. 2195.	• • • • • •		HUTFLOW -	AVE.	NSTDL	186.50	254.00	761.	186:	SPUID 6.				2451 9671
- 2000 - 1000 -	9452. 7440. 9456. 4459.	2225		•	ROUTED BUTFLOW ISTAG ICO	61058	ASTPS 1			310.	174.	CREL S				16979
20102- 17213- 14357-	9655. 7815. 6009. 4779.	CFS CMS INCKES INCKES AN AN AN				#F058		186.08	8051.60	:	164.	~				162.
	9858. 7988. 6218. 1985.		# # # # # # # # # # # # # # # # # # #					174.00	. 90.1787						•	200.
	6 P J J		•						FLOW 7	CAPAC 1 17=	FLEVATIONS		·	•		**
. <b>.</b>		,	•					STAGE	<u> </u>	~	ב			•	•	• .

THE COLOR OF THE C		· · · · · · · · · · · · · · · · · · ·		2499	2048.	1664.	- 1521-	19601	. 45		•	789.	19020			978.	952.	929.	886	12	Š		186.3	7-564	18903	166.9	18866		8	- 1	25				The second of th	-			* * * * * * * * * * * * * * * * * * *			4.	288	6.052 6.052	4557	3792.		2300
1, 1, 2, 1, 1, 2, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1,		- 01 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	- 2000	- 9 - C - C - C - C - C - C - C - C - C	2090.	1786.	-		879					4271		980	955	58		672.	856.		186.3	193.7	189.3	169.0	188.6	168.0	167.8	187.5	187.				•	•						?	2:	6987	1642.	3862	3228.	2195
10.00 10.00		:										•		9411	16191	- 1986 - 1986	957.		• 116	- 476	857.		186.3	193.2	• •	-	-		•		87.		ં ₹	390264.	11052.	75.84	- 96765-	119357.			FE8-		. •	-	;			ı
THE COLOR OF THE C													7 7	2:								;	186.	192.	189.	189.	188		187	187	187.		-HOUR 10	6321.	236.	20.62	9513.	1873.	1. PATIO	•	I L		•	-				
TAN THE PARTY OF T		:										•	-		-	•						791	<u> </u>				•	•	•			.•	-HOUR 3 72	2930	• • • •				•		MODE CAR	3						
75.5. 11.7. 1147. 2551. 2551. 2551. 2557. 2564. 2564. 2557. 2564. 2557. 2564. 2565.	•	7. 4.	57.29 ·	2746	9922	1847	1493	1200	27.6			_		1176								18	_	<b>~</b> .	•		~ .	-	. ~						-53						7					•		
15.5. 11.1.	1												•	~ •		-																:	PEAK	15438.	.437.	•									•			
15.5. 11.2 255.4. 204. 275. 204. 275. 204. 275. 200. 285. 200. 1630. 1590. 1850. 100. 1850. 100. 1860. 3 186. 1860. 3 186. 1860. 3 186. 1860. 3 186. 187. 3 187.																_																HE 57.			CXS	4 TE	AC-FT	# 20 # 20 # 30							•			
PEAK OUTFLOW 1		7.14	-,	`	~	-		•	-	•		7.0	910	1320	1067		973	*		200	198		_		-	-		-	-	_		5438. A			•			36#L						_	•			
		·	3548	2957:	2452.	2007	1410		1072			.785.	795	1369	1086.	1007	975	75.	927		169		186.3	106.4	189.9	180.3	188.9		1.66.4	167.7	187.5	22					•				•	,	151	218-	5810	4473.	3724	2574
																																				,									•		•	

					i, i		i		į.
1	•				ļ <b>ļ</b> .		• 1		
100   100	•								
100   100	•						!	1 : 1	i
100   100	1	• •	1 1 .	'   <u> </u>				•	
100   100		, ,		1					
10   10   10   10   10   10   10   10	3 × 1		857 455 854 855 854 855	900000		·	189	2013	22.5
1711   1112   1124						-			
1711   1112   1124		223.	5326	200000	-64-0				223
1311.   1157.   1244.   1245.   1247.   1315.   1317						· i · · · · · · · · · · · · · · · · · ·	-	1 2 2 2 2 2 2 2 2	111
1311.   1157.   1244.   1245.   1247.   1315.   1317	• • •		••••			W 2 2 7 7 2 2		1 1 1	
1311.   1157.   1244.   1245.   1247.   1315.   1317		2000	999	1199	2555	2004 2004 2004 2004 2004 2004 2004 2004	: 6	1000 1000 1000 1000 1000 1000 1000 100	1016
11   11   11   11   11   11   11   1	•					ੜ :			; ; -
1116.   1515.   1514.   1515	362	100.	52.	W 40 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	2222	101	. 💲 🕹		267.
THE COLOR CO	115					200 E			4444
110.   100.			:::::::	~~~	~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~	200 00 00 00 00 00 00 00 00 00 00 00 00	SRAP.		
1111   1675   1534   1264   1274	1232	2000		900000000000000000000000000000000000000			· •	2 0 4 7 C 0 4 C	200 . 200 . 200 .
1111   1675   1534   1264   1274		ė.		<b>a</b>		1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1			•
1111   1675   1536   1560		S 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	125. 125. 1861.	S 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2		~		5225	275.
786. 789. 1893. 1809. 18	1 7 8 7	-2224			4 # # # # # # # # # # # # # # # # # # #	•	•	តិសិសិទិទាគីលិខិ	NAAA.
1101.   107.   103.   174.   174.   171.   171.   171.   172.   1724.   171.   171.   172.   1724.	:223			778778	E N = F + D		. 9		
1711   1675   1536   1546   1711   1675   1536   1546   1711   1675   1536   1546   1711   1675   1536   1546   1711   1675   1546   1711	32.0			30765		¥	13	1777 T	
1111	•				_	459	•		•
784. 789. 1316. 1675. 1316. 13	755		£ 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5	25.00		<b>2</b>		525. 525. 535. 535. 535. 535.	
1711. 1675. 1716. 1875.	. 222		4	22222				~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~	Need
1116. 1111.				7.5.47.4		ğ 4,	÷	******	1124
1111. 1711.		C 8 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0		44866	122555 7	Ē	11	25.0 25.0 25.0 25.0 25.0 25.0 25.0	137
	•		•						
	711.	786. 797. 889.	25.55	7 7 9 7 9 7 9 9 9 9 9 9 9 9 9 9 9 9 9 9		. •	156.		23. 25. 35.
·		# # # # # # # # # # # # # # # # # # #	A	A A A A A A	"	•		# *********	~~~
·	; •		•	•		•			
·				•	. ¥		•		
the state of the first term of the first terms of t	• •		-	:	, be	W .	•		·
	į	,	1 1 1	1.	1 1 1 1	·		11	l

	433.	19793 8972 7470 5241	41556 32986 25316 19246	1766 1395 1295 1209 1159 1114
	123	9992 9138 7607 6361 5221	4242- 5386- 2597- 1983-	1763: 1432: 1432: 1274: 1163: 1116: 1033:
4879230 138160 138160 138160 138160 138160 1492130	8 414 35611	11208. 17108. 1717. 6481. 5328.	2665. 2655. 2639.	12680- 12680- 12680- 112880- 111880- 1
# O F		11406. 14406. 14806. 15600.	4422. 3558. 2736. 2098.	816- 1553- 1553- 1286- 1128- 11173- 1092- 1090-
25	HYDROGRAP OV 100. 21554.	1 4 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5	451 264 266 215	
TH # 0.000	-0F-PER100 0UTFL 397- 13170-			46.000 .000 .000 .000 .000
4	398	12111 12111 13111 1313 1313 1313 1313 1	4707. 5809. 2962. 2279.	11266 11266 11266 11266 11166 1166 1166 1166 1166 1166 1166 1166 1166 1166 1166 1166 1166 1166 1
	. 2607		• • • • • • • • • • • • • • • • • • •	
4 3	9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9		4408. 5981. 3126. 2463.	11 11 12 12 13 13 13 13 13 13 13 13 13 13 13 13 13
2	460 460 460 460	100000 100000 100000 100000 10000	5010. 4067. 3212. 2466.	816. 1737. 1737. 1262. 1264. 1194.
189.5 189.7 189.6 189.6 189.5 189.5 189.9 189.9 189.9 189.9 189.9 189.9 189.9 189.9 189.9 189.9 189.9 189.9 189.9 189.9 189.0	189.5 189.7 187.7 187.6 189.6 189.7 189.7 189.9 199.9	180-1 180-1	197.2 189.7 189.7 189.7 189.7 189.6 189.5 189.5 189.5 189.5 189.6 189.9 189.7 189.7 189.7 189.7 189.9 189.9 189.9 189.9 189.9 189.9 189.9 189.9 189.9 189.9 189.9 189.9 189.9 189.9 189.9 189.7 189.9 189.9 189.9 189.9 189.9 189.9 189.9 187.9	1975 1975 1975 1975 1975 1975 1975 1975

1912-1 191	190.6	190.3	,	188.8 168.8	166.4	.188.0 - 187.		The second secon	,	The second of th		And the second s	**			A 4.00	77421. 76969	33174 30135	18215.	15205-	12596 12352	8363. 81	6622 64	3956. 50			2253 22	1706.	1532. 1526	1396.	1322. 1314	1252.	1189. 1183	1126. 11	1021.		187	203.8
192.	.9 190	190	C = -	183	188.	188	•	TOTAL VOLUME	97910	27725-	. 2	299430		10 8	ORDINATES	زر				1548	75		19 6801	59. 5		61. 862	44. 218	175	1540	<b>-</b>		- 125	1195	41. 1134	30. 102		!	1.3 203.0
~ · ·		-	. 6.68	186.0	88.5	86-1 18		-HOUR 12-HOUR	211		96	64318. 125690. 79335. 155037.		DAM. PLAN 1. RATTO	ND-OF-PEPIOD HYDROGRAPH ORD	. •	79. 59	•	193234 22739	58.	15.	57. 107 02. 87	153. 69	99. 54		165	1845. 20.	868.		183.	3446	275. 1	207- 12	~ .	035. 10		87.1	199.0 201
	161	0.1	6.	2 4		87		26				18781- 64. 23167- 79		STATION	END-0F-PEP 10	OUTFLOU	23265	6.6	~ -			_	132	5735	• • • • • • • • • • • • • • • • • • • •	STOR	9. 1618.		1560	-	1	-		<b>~</b> .	1040		187.1	.9 196.3
	-		200		88.6		57.88 HOURS	PEAK	38697.	1096.						496	13		24458. 24145. 2042. 19978.		•	11641. 11409. 9479. 9281.			•	9	151. 850. 181. 1339.				366.		-	165.	60 T		187.1 187.	89.8 192.9
	91.2				188.7		38697. AT TIME		CFS		2	THOUS CU M							25145. 24			11875. 11					60 P				1373.						87.1	166.1
193,1	191.3	1.00.1	190.2	4° F 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8	1886.7	188.3			٠							9 9 9	1124	10737.	27478	17558.	14656.	12112.	8011.	6275.	74		657	2178.	. 1621.	1519	1381	1307.	239	~ •	1115.	}	107.1	N C. C.

								1			į			:
									•		ł			
					ŧ				١					ļ.,
	ņ	9	e.	-	٠,		•	•			!			i
	195	192	161	191.1	190	9	101	169	i		i			1
									t		Ì			į
	193.6	192.7	19159	191.1	190.4	. 401	10601	169.1						:
									•		!			i
	191.7	192.8	192.0	191.2	190.5		187.8	169.2	. VOLUME	55575	19.01	381.36	186602.	600215.
:	. 4.5.	92.9	42.0	191.3	\$ 06		6.7.9	89.2	TOTAL		•			
-	-	7	7	· <u>-</u>	=		=	Ä	5. 5.	.91	83	181	55.	2.
	95.7	93.0	92.1	191.3	400		D. 6.0	89.3	72-HOUR	121	~	198	2537	3130
-	=	-	Ž	<u>۔</u>	-	•	<del>-</del>	Ξ.		9.	9	55	76.	
	= • •	15.1	2.2	1915			e. 0	19.3	24-HOUR 65328.	18	ě	101	1295	1598
-	-	-	-	-	. =	•	_	=	20 S	٠	9	5	.6	•
-	•	_			•		•	•	6-HOUR	21.	ä	29	375	463
•	***	193	199	191	90		190.	189.	S					
									DO HOURS FEAK	192				
:	-		•	. 4			-	·	57.90	~				
?	-			101		-	7 90	189	٠,	· ca	s	<b>£</b>	-	<b>.</b>
									77421. AT TIME	CHS	SHO	Ŧ	-F	THOUS CU P
•							6.2	189.5	14		=			900
<u>-</u>	1.3				•	-	13	28	:					Ξ
						_	_	_	174					
:	44					7.	90.2	189.6						
_	_	-	•	٠.	• •	_	-	-	2					
			,						FLO					
									TOO I					
									PEAK OUTFLOW IS					
									Pa-					

ŀ

:

• ;

----

ļ

PEAK FLOW AND STORAGE (END OF PERIOD) SUMMARY FORMULTIPLE PLAN-RATIO ECONOMIC COMPUTATIONS Flows in cubic feet per second (cubic meters per second) Area in Square Miles (square Milometers)

						RATIOS API	PLIEU TO FL	SAO			
OPERATION	STATION	AREA	PLAN	RATID 1 8.20	RATIO 2 0.21	RATTO 3 0.22	PLAN RATIO 1 RATIO 2 RATIO 3 RATIO 4 RATIO 5 RATIO 6 RATIO 7 RATIO B B 0.20 0.21 0.22 0.23 0.24 0.25 0.50 1.00	RATIO 5 0.24	AATTO 6	AAT10 7 0.50	RATIO 8
HYDROGRAPH AT LKFLUR 179.00	LKFLYR	179.00		1928.	2024.	2120.	2217.	2313.	2410.	4819.	4819. 9638. ( 136.46)( 272.92)(
ROUTED TO	SARRIV	SARRIV 179.00		1912.	2008.	2104.	2199.	2295.	2391.	4811.	4811. 9628. 136.22)( 272.64)(
HYDROGRAPH AT LURBSM 429.86	LURBSN	429.66	<b>-</b>	15437.	16209: 458.98)(	16981.	17752.	18524.	19296.	38592.	19296. 38592. 77184. 546.41)( 1092.81)( 2185.62)(
COMPINED.	DAM	OAM 608.88	~	15506.		16281. 17056. 461.02)( 482.97)(		18607.	. 19582. 548.83)(	38764.	17831, 18607, 19582, 38764, 77528, 504,9331 526,8831 548,8331 1097,6731 2195,5431
*001EB 10	DAM	DAN 683.00		15438. 16213. 17010. ( 437-15)( 459-09)( 481-66)(	16213.	17010.	17798.	18569.	19351.	38697.	17798. '18569. 19551. 38697. 77421. 503.99)( 525.81)( 547.39)( 1095.78)( 2192.31)(


# PLAN 1 STATION SARRIV


TIME	HOURS	96.00	96.00	96.00	96.00	96.00	96.00	87.00	84.00
MAXIMUM	STAGE+FT	213.0	213.0	213.1	213.2	213.3	213.3	214.8	:
MAXIMUM	FLOHOCFS	1912.	2008.	2104.	2199.	2295.	2391.	4811.	9628
•;	RATIO	0.20	0.21	0.22	0.23	0.24	0.25	0.50	1.00


ENT	,								,		
EMBANKMENT		-									
	TIME OF	JL URE	OURS		•	•	•	•	•	•	•
LEFT	Ī	FA	Ĩ			•	_			_	_
TOP OF DAM — C LEFT 193.80 1413. 15820.	TIME OF	MAX OUTFLOW	HOURS	57.00	57.00	57.00	57.00	57.00	57.00	57.00	57.00
:	DURATION	OVER TOP	HOURS	•	6.00	6.00	12.00	12.00	12.00	42.00	126.00
SPILLWAY CREST 186.00	MAKIMUM	POLIFICA	CFS	15438.	16215.	17010.	17798.	.18569.	19331.	38697.	77421.
4ALUE ••• 61• 0•	MAXIMUM	STORAGE	AC-FT	1402.	1423.	1440.	1456.	1472.	1486.	1783.	2253.
INITIAL VALUE 186.00 761.	MAXIMUM	DEPTH	OVER DAM		0.12	0.33	0.52	0.70	0.88	4.42	10.05
ELEVATION Storage Outflou	MAXIMUM	RESERVOIR	H. S.ELEV	193.67	193.92	194.13	194.32	194.50	194.68	198.22	203.85
	RATIO	90	PRF	0.20	0.21	0.22	0.23	0.24	0.25	0.50	1.00
•		•									
PLAN											


NO FLASHBOARDS FLOOD GATE CLOSED


AIN MILL DAM














#### STREAMS TRIBUTARY TO ST. LAWRENCE RIVER 04273500 SARANAC RIVER AT PLATTSBURGH. NY

LOCATION.--Lat 44°40'54", long 73°28'18", Clinton County, Hydrologic Unit 02010006, on right bank at Plattsburgh, 600 ft (183 m) downstream from Imperial Paper and Color Corp. dam, 3.0 mi (4.8 km) upstream from mouth, and 5.5 mi (8.8 km) downstream from Mead Brook.

DRAINAGE AREA. -- 608 mi<sup>2</sup> (1,575 km<sup>2</sup>). Prior to Nov. 12, 1919, 607 mi<sup>2</sup> (1,572 km<sup>2</sup>).

PERIOD OF RECORD. -- March 1903 to September 1930, October 1943 to current year. Published as "mear Plattsburgh," 1903-30.

REVISED RECORDS.--WSP 345: Drainage area. WSP 384: 1909-10 (monthly discharge only). WSP 1387: 1907-8. WSP 1437: 1908 (minimum daily only).

GAGE..-Water-stage recorder. Datum of gage is 155.74 ft (47.470 m) National Geodetic Vertical Datum of 1929.
Prior to Nov. 12, 1919, nonrecording gage and Nov. 12, 1919 to Sept. 30, 1930, water-stage recorder, at site 1.5 mi (2.4 km) upstream at different datum.

REMARES. -- Records good except those for winter periods, which are fair. Considerable diurnal fluctuation caused by power and industrial operations. Slight regulation by storage in Upper and Lower Saranac Lakes and elsewhere. During year, city of Plattsburgh diverted an average of 3.43 ft<sup>3</sup>/s (0.097 m<sup>3</sup>/s) from Saranac River and Mead and West Brooks, tributaries above station, for municipal supply. About 1 ft<sup>3</sup>/s (0.028 m<sup>3</sup>/s) diverted from Great Chasy River basin into Saranac River for water supply of State Institutions at Dannomera.

AVERAGE DISCHARGE. -- 63 years, 835 ft $^3$ /s (23.65  $m^3$ /s).

EXTREMES FOR PERIOD OF RECORD.--Maximum discharge,  $11,500 \text{ ft}^3/\text{s}$  (326 m<sup>3</sup>/s) Apr. 8, 1928, from computation of flow over dam and through waste gates and powerplant; minimum daily, 3.6 ft<sup>3</sup>/s (0.102 m<sup>3</sup>/s) June 26, 1979.

EXTREMES FOR CURRENT YEAR. -- Maximum discharge, 5,930 ft $^3$ /s (168 m $^3$ /s) Apr. 3, gage height, 7.92 ft (2.414 m); minimum gage height, 0.64 ft (0.195 m) June 24; minimum daily discharge, 3.6 ft $^3$ /s (0.102 m $^3$ /s) June 26.


		DISCHA	AGE. IN C	UBIC FEET	PER SECO	ND. WATER	YEAR OCT	OBER 197	O TO SEPTE	HOER 1979		
DAY	OCT	MOV	DEC	JAN	FED	MAR	APR	MAY	JUN	JAR.	AUS	SEP
1 2	248 393	582 529	37 <b>5</b> . 346	562 657	593 681	545 616	3470 3140	2540 2210	1230 1100	a*	291 245	599 534
3	397	523	291	1240	566	599	4940	1990	799	124	397	472
•	443	513	149	1000	561	593	3700	2040	908	112	443	477
5	425	- 513	221	945	. 427	- 724	3166	1990	762-	142	371	466
•	306	500	261	840	940	1050	2730	1900	795		367	_ *** .
?	440	513 518	363 503	849 864	548 548	1940	2410 2100	1606 1500	717 711	104	440 330	1400
÷	470	. 523	443	893	500	1560	1940	1446	693	87	250	1240
10	450	· 516	468	455	620	1550	1050	1300	661	67	วันว	976
11	360	443	503	856	600	1540	1730	1300	693		290	968
12	331	415	472	701	600	1340	1720	1250	457	50	295	956
13 14	415	477	492	768 738	500	1130 1120	1730	1260	633 562	91	534 397	795 768
iš	566 821	<b>622</b> 711	518 518	864	700 546	1140	1940 2190	1240	545	64 57	264	1050
16	991	502	518	893	500	1170	2350	1130	463	42	295	1040
iř	471	705	503	950	489	iiio	2630	1030	313	221	304	963
10	922	635	460	762	470	991	2460	995	462	407	331	907
19	1010	740	453	676	450	1050	2330	740	489	411	591	935
20	006	539	305	954	411	1050	2210	717	137	363	305	796
<b>21</b>	717	523	331	762	518	1150	\$130	724	44	- 305	293	796
23	926	518	546	775	448	1400	2140	705	•	542	327	740
<b>*</b>	984 622	467 663	534 467	900 762	477 503	1940 2500	2150 2190	616	72 <b>5</b> 4	233 196	296 305	711 603
ž	472	539	500	667	466	4100	2000	762	· · · · · ·	206	305	603
24 27	446	482	539	762	534	4390	2050	1020	3.6	295	900	693
27	327	472	510	775	539	3480	\$100	1010	47	245	993	683
20	327	296	510	720	546	2620	3160	1110	92	375	686	977
29 30	492 599	23e 367	513 550	795 726		2000 2060	3380 2930	1140 1260	62 60	367 250	687 934	946 980
ji 💮	616		518	•63	==	2440		1340		301	993	***
TOTAL	17095	15054	13741	25226	19103	50518	75070	39996	13771.7	5090	12236	23040
HEAM	570	520	443	014	542	1630	2502	1277	489	190	395	700
MAX	1010 -	635	550	1546	700	4390	4960	2540	1530	407	020	1400
MIM	246 -	530	149	205	411	549	1720	616	3.4	42	245	466

CAL TR 1978 TOTAL 348636.0 MEAN 955 MAX 4710 MEN 70

### APPENDIX D STABILITY COMPUTATIONS

NAIN MILL DAM
APPROXIMATE CROSS SECTION OF SPILLWAY PORTION

SCALE 1"= 5"
(BASED ON SKETCH FROM CONSERNATION COMMISSION RELIER)



#### STRUCTURAL STABILITY ANALYSIS

This analysis was based on an approximate cross section of the spillway section shown on a 1913 Conservation Commission inspection report. A normal analysis was performed including both overturning and sliding analyses. Since the foundation conditions were unknown, full uplift was assumed at the upstream toe, decreasing to the tailwater pressure at the downstream toe.

#### ANALYSIS CONDITIONS

- 1. Normal conditions; 2.5 feet of flashboards in place; water surface at top of flashboards
- 2. Water surface at spillway crest (no flashboards) with an ice load of 5,000 pounds per linear foot
- Flood flows; water surface at top of embankment section;
   7.8 feet above spillway crest
- 4. Normal condition as in case No. 1, with a seismic coefficient of 0.10.

#### STABILITY ANALYSIS PROGRAM - WORK SHEET

INPUT ENTRY		,	ANALYSIS CONDITION				
Unit Weight of Dam (K/ft <sup>3</sup> )	0	0.15	0.15	0.15	0.15	5	
Area of Segment No. 1 (ft <sup>2</sup> )	1	82,5	82.5	82.5	82.5	-	
Distance from Center of Gravity of Segment No. 1 to Downstream Toe (ft)	2	(3	is	13	13		
Area of Segment No. 2 (ft <sup>2</sup> )	3	66	66	66	66		
Distance from Center of Gravity of Segment No. 2 to Downstream Toe (ft)	4	9	9	9	9		
Area of Segment No. 3 (ft <sup>2</sup> )	5	75	75	75	75		
Distance from Center of Gravity of Segment No. 3 to Downstream Toe (ft)	6	5	5	5	5		
Base Width of Dam (Total) (ft)	7	18	18	18	18		
Height of Dam (ft)	8	22	22	22	22		
1ce Loading (K/L ft.)	9	_	5	_	_		
Coefficient of Sliding	10	0.65	0.65	0.65	0.65		
Unit Height of Soil (K/ft <sup>3</sup> ) (deduct 18)	ii	0.055	,055	,055	.055		
Active Soil Coefficient - Ka	12	-		-	_		
Passive Soil Coefficient - Kp	13	~	_				
Height of Water over Top of Dam or Spillway (ft)	14		_	5,3	~		
Height of Soil for Active Pressure (ft)	15	~		_	-		
Height of Soil for Passive Pressure (ft)	16		_		<u> </u>		
Height of Water in Tailrace Channel (ft)	17	2	2	2	2		
* Weight of Water (K/ft <sup>3</sup> )	18	0.0624	0,0624	0.0624	0,0624		
Area of Segment No. 4 (ft <sup>2</sup> )	19	-		-	_		
Distance from Center of Gravity of Segment No. 4 to Downstream Toe (ft)	20		_		-		
Height of Ice Load or Active Water (ft) (does not include 14)	46	24.5	22	24.5	24.5		
Seismic Coefficient (g)	50		-	_	0.1	,	
RESULTS OF ANALYSIS		· • •				1	
Factor of Safety vs. Overturning		0,94	0.81	0.76	38.0		
Distance From Toe to Resultant		-099	-3,46	-5.28	-2.10		
Factor of Safety vs. Sliding		0,65	0.65	0,47	0.51		

APPENDIX E

REFERENCES

#### APPENDIX E

#### REFERENCES

- 1) H.W. King and E. F. Brater, <u>Handbook of Hydraulics</u>, 5th edition, McGraw-Hill, 1963
- 2) The Resources of the New England-New York Region;
  Part 2 Chapter 27; Lake Champlain Drainage Basin, NY-VT;
  by New England- New York Inter-Agency Committee, 1954
- 3) University of the State of New York, Geology of New York, Education Leaflet 20, Reprinted 1973.
  - U. S. Army Corps of Engineers:
- 4) HEC-1 Flood Hydrograph Package Dam Safety Version, September 1978
- 5) Engineering Manual 1110-2-1405; Flood-Hydrograph Analyses and Computations, August 1959.
  - U.S. Army Corps of Engineers; New York District:
- 6) <u>Phase I Inspection Report Lake Flower Dam;</u> by Dale Engineering Co., September 1980.
- 7) <u>Upper Hudson and Mohawk River Basins Hydrologic Flood Routing Models</u>, Resource Analysis, Inc., October 1976.
- 8) U.S. Department of Agriculture, Soil Conservation Service; National Engineering Handbook; Section 4 Hydrology, August 1972.
- 9) U.S. Department of Commerce; Weather Bureau: Hydrometeorological Report No. 33: Seasonal Variation of the Probable Maximum Precipitation East of the 105th Meridian for Areas from 10 to 1,000 Square Miles and Durations of 6,12,24, and 48 Hours, April 1956.
- 10) U.S. Department of Interior; BUREC: <u>Design of Small Dams</u>. 2nd ediction, (rev. reprint), 1977
- 11) U.S. Geological Survey; <u>Water Resources Data for New York</u>, Water Year 1979, Volume 1; Report NY-79-1, 1980.

APPENDIX F
DRAWINGS

VICINITY MAP MAIN MILL DAM I.D.NO. NY262 BEEKM DAM SITE BARANAC TERRY MOUNTAIN CHESTERFIELD Hutternal Pond

NOTICE: After filling out one of these forms as completely as possible for each dam in your district, return it at once to the

## STATE OF NEW YORK CONSERVATION COMMISSION ALBANY

DAM REPORT

October 9th, 1913

Conservation Commission.

Commercia:

Division of Inland Waters.

the Frage state Surface Cost Main Down.

The distance of Surface Cost of Plattsbury


The distance of Surface Country of Plattsbury

The dam is now owned by Programs Falls & Plattsbury.

As it now stands, the spillway portion of this dam is built of Llove.

As nearly as I can learn, the character of the foundation bed under the spillway portion of the fam is Sieve Stone and under the remaining portions such foundation bed is All Estimation of the Standard or Assert

and the where portions are mile of Stone & Garthow Shore portions




The collinery on weets
The total length of this dam is about 600 ft feet. The spillway or waste-
weir portion, is about $+85$ 300 feet long, and the crest of the spillway is
about 4 feet below the top of the dam.
The number, size and location of discharge pipes, waste pipes or gates which may be
used for drawing off the water from behind the dam, are as follows: 3 Hater althoral
State briefly, in the space below, whether, in your judgment, this dam is in good condition, or bas condition, describing particularly
State briefly, in the space below, whether, in your judgment, this dam is in good condition, or bad condition, describing particularly only leaks or cracks which you may have observed.)
and the second second
Tolio munsory dam, 18' duet ut Bollon
le hate ut Top, au fint- Class Condition
cag. 4,1920
Structure in good condition. Danger in case of brea
il bonder at ende.
Swinde Sach, I. y.
Twende Sante, to If.
Reported by John - Coursey from Signature
Reported by ome Signature (Signature)
(Address -Street at a number, P. U. Stra or R. P. D. route)


Name of place)

(SEE OTHER SIDE)

(In the space below, make one sketch shewing the form and dimensions of a cross section through the spillway or waste-weir of this dam, and a second sketch showing the same information for a cross section through the other portion of the dam. Show particularly the greatest height of the dam above the stream bed, its thickness at the top, and thickness at the bottom, as nearly as you can learn.



In the space I low, make a third sketch showing the general plan of the dam, and its approximate position in relation to buildings or the second the vicinity.



18 20-11-2004 (14-10- 2)

Fill cut a form as complete as possible for each dam in your district and send to State Conservation Commission, Albany, N. Y.

- 1 Name and address of owners Progressive Pulp+ Paper Co Platteburghin 4
- 2. Date of construction.
- 3. Uses of impounded water paper mill
- p. Than a or of foundation hed Accele ...
- 5. Acuterial of vaste spill. cut stone
- 1 Longth of wests and depth below dam 100' 3' below dam
- 7. Total length of dam including waste 3.50'
- & Not red of dom count stone
- o Discherges, six and location hipe of in diameter 25 shiere

Blic sket b section of waste and section of dam, with greatest heights and top thickness of contempths kness. On opposite side sketch general plan of dam and give distance from a lordge or from a tributary stream.

entston > 15"

fell.

dam

Nicerature add as and date t

July 28/9/2.

| hulkleads . . . . ...